

5.4 Convenience Feature (CF)
Models 202, 208, 210 as of M.Y. 1998

Page

Diagnosis

Function Test	11/1
Diagnostic Trouble Code (DTC) Memory	12/1
Recalling Actual Values with HHT	13/1
Complaint Related Diagnostic Chart	14/1

Electrical Test Program

Component Locations	20/1
Connection of Components	21/1
Preparation for Test	22/1
Test	23/1
Version Coding	31/1

Notes regarding Convenience Feature:

Actuation of power windows via lower control field control module (N72)

The desired adjustment of the power window motor is sent from the lower control field control module (N72) via the CAN bus to the corresponding door control module. These in turn activate the power window motor itself.

Power window motor actuation via power window switch in the rear doors

The power window switches located in the rear doors, act directly on the rear driver/passenger-side door control modules (N69/3, N69/4). Except Model 208.4.

Child safety lock switch (N72s5)

With a deactivated child safety lock switch, the lower control field control module sends the message "Release rear power window motor" via the CAN bus. This message is recorded by the rear driver/passenger-side door control modules (N69/3, N69/4) and can be activated by pressing the left/right rear power window switches (S21/3, S21/4). Except Model 208.4.

Convenience Opening

Opening is accomplished when the front driver-side door control module (N69/1) first receives a valid "open" signal and then a continuous IR signal (button kept depressed) from the electronic ignition lock control module (N73). The same opening conditions apply for the front passenger side door control module (N69/2).

Convenience Closing

Closing is accomplished when the front driver-side door control module first receives a valid "close" signal and then a continuous IR signal (button kept depressed) from the electronic ignition lock control module (N73). The same closing conditions apply for the front passenger-side door.

Function Sequence

The activated (via IR transmitter key) left/right front door IR receiver (A26/1, A26/2) located in the door, sends a signal to the corresponding left/right front door control module (N69/1, N69/2). As a result, the left/right front door control module sends a CAN message to the electronic ignition lock control module (N73). The electronic ignition lock control module in turn, checks the coded signal and if a valid code exists, sends a the CAN message "release granted" back to the left/right front door control module. Should a parallel message "Door closed" (along with the CAN message) be received by the left/right front door control module, from the PSE control module (A37), the left/right front door control module will act directly to its corresponding power window motor and at the same time send the received CAN message to the other left/right door control module, as well as to the roof control panel control module (N70): "open" and "close".

The sliding-pop-up roof and power window motors are activated directly from their corresponding control modules



The convenience feature function is only possible via the infrared signal and functions in this mode as long as the IR transmitter button is depressed.

Diagnosis – Function Test (Convenience Feature)

Test step/Test scope	Test condition	Nominal value	Possible cause/Remedy ¹⁾
⇒ 1.0 Power windows	Ignition key position “1”		
Open side windows	Press back of power window switch down to first detent.	Side window opens , as long as switch is depressed.	14 Complaint No.’s 4, 8, 12, 16
Open side windows (one-touch opening)	Press back of power window switch down past first detent.	Side window opens completely (switch does not have to be held depressed).	14 Complaint No.’s 5, 9, 13, 17
Close side windows	Press front of power window switch down.	Side window closes , as long as switch is depressed.	14 Complaint No.’s 6, 10, 14, 18
Close side windows (one-touch closing)	Press front of power window switch down past first detent.	Side window closes completely (switch does not have to be held depressed).	14 Complaint No.’s 7, 11, 15, 19

1) Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1999

Diagnosis – Function Test (Convenience Feature)

Test step/Test scope	Test condition	Nominal value	Possible cause/Remedy ¹⁾
⇒ 2.0 Convenience closing Side windows and sliding/pop-up roof	Using IR transmitter or electronic vehicle key ²⁾ , lock front doors or trunk lid and hold in this position. (Windows synchronized, 22).	Open sliding/pop-up roof or open side windows close .	14 Complaint No. 2
⇒ 3.0 Convenience opening Side windows and sliding/pop-up roof	Using IR transmitter or electronic vehicle key ²⁾ , unlock vehicle and hold in this position.	Closed sliding/pop-up roof or open side windows open .	14 Complaint No. 1

1) Observe Preparation for Test, see 22.

2) (only ) , M.Y. 1998

Diagnosis – Function Test (Convenience Feature)

Test step/Test scope	Test condition	Nominal value	Possible cause/Remedy ¹⁾
⇒ 4.0 Sliding/pop-up roof	Ignition key in position “1”		
Open sliding roof	Push sliding/pop-up roof switch toward rear.	Sliding roof opens.	14 Complaint No. 23, 24
Open sliding roof (Model 210 Wagon only)	Push sliding/pop-up roof switch toward rear and hold in this position. Push sliding/pop-up roof switch toward rear second time.	Sliding roof opens. Sliding roof now opens completely.	Check coding in electronic ignition lock control module (N73).
Close sliding roof	Push sliding/pop-up roof switch toward front.	Sliding roof closes.	14 Complaint No. 25
Open pop-up roof	Push sliding/pop-up roof switch up.	Pop-up roof opens.	14 Complaint No. 26
Close pop-up roof	Pull sliding/pop-up roof switch down.	Pop-up roof closes.	14 Complaint No. 27

1) Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Model 208.4 as of M.Y. 1999

Diagnosis – Function Test (Convenience Feature)

Test step/Test scope	Test condition	Nominal value	Possible cause/Remedy ¹⁾
⇒ 1.0 Power windows	Ignition key in position “1”		
Open left rear window	Press back of power window switch (N72s3) down to first detent.	Side window opens , as long as switch is depressed.	14 Complaint No. 15
Open right rear window	Press back of power window switch (N72s4) down to first detent.	Side window opens , as long as switch is depressed.	14 Complaint No. 20
Close left rear window	Press front of power window switch (N72s3) down to first detent.	Side window closes , as long as switch is depressed.	14 Complaint No. 15
	Press front of power window switch (N72s3) down past first detent.	Side window closes , as long as switch is depressed. Window does not have one touch closing.	
Close right rear window	Press of front power window switch (N72s4) down to first detent.	Side window closes , as long as switch is depressed.	14 Complaint No. 20
	Press of front power window switch (N72s4) down past first detent.	Side window closes , as long as switch is depressed. Window does not have one touch closing.	

1) Observe Preparation for Test, see 22.

Diagnosis – Function Test (Convenience Feature)

Test step/Test scope	Test condition	Nominal value	Possible cause/Remedy ¹⁾
⇒ 1.0 Power windows	Ignition key in position “1”		
Open left rear window (one-touch opening)	Press back of power window switch (N72s3) down past first detent.	Side window opens completely (switch does not have to be held depressed).	14 Complaint No. 15
Open right rear window (one-touch opening)	Press back of power window switch (N72s3) down past first detent.	Side window opens completely (switch does not have to be held depressed).	14 Complaint No. 20
Open left front window	Press back of power window switch in center console (S21/1) down to first detent.	Side window opens , as long as switch is depressed.	14 Complaint No. 5
Open right front window	Press back of power window switch in center console (S21/2) down to first detent.	Side window opens , as long as switch is depressed.	14 Complaint No. 10
Close left front window	Press front of power window switch in center console (S21/1) down to first detent. Press front of power window switch in center console (S21/1) down past first detent.	Side window closes , as long as switch is depressed. Window does not have one touch closing. Side window closes , as long as switch is depressed. Window does not have one touch closing.	14 Complaint No. 5

1) Observe Preparation for Test, see 22.

Diagnosis – Function Test (Convenience Feature)

Test step/Test scope	Test condition	Nominal value	Possible cause/Remedy ¹⁾
⇒ 1.0 Power windows	Ignition key in position “1”		
Close right front window	<p>Press front of power window switch in center console (S21/2) down to first detent.</p> <p>Press front of power window switch in center console (S21/2) down past first detent.</p>	<p>Side window closes , as long as switch is depressed. Window does not have one touch closing.</p> <p>Side window closes , as long as switch is depressed. Window does not have one touch closing.</p>	14 Complaint No. 10
Open left front window (one-touch opening)	Press back of power window switch in center console (S21/2) down past first detent.	Side window opens completely (switch does not have to be held depressed).	14 Complaint No. 5
Open right front window (one-touch opening)	Press back of power window switch in center console (S21/2) down past first detent.	Side window opens completely (switch does not have to be held depressed).	14 Complaint No. 10

¹⁾ Observe Preparation for Test, see 22.

Diagnosis – Function Test (Convenience Feature)

Test step/Test scope	Test condition	Nominal value	Possible cause/Remedy ¹⁾
⇒ 2.0 Central locking of all power windows	Ignition ON Soft top must be very nearly open or closed. Press soft top switch (S84) down twice within 0.5s and keep depressed.	Before the soft top starts moving, the side windows are first completely opened. The rear side windows will open first.	14 Complaint No. 4
⇒ 3.0 Convenience opening/closing of all power windows	Ignition OFF Side windows: OPEN Convenience closing: Using IR transmitter, lock vehicle and hold in this position. Convenience opening: Using IR transmitter, unlock vehicle and hold in this position (longer than 5s).	The Operation of the soft top is inhibited if the power window switches or the soft top switch are pressed. All open side windows will close. All side windows will open.	14 Complaint No. 4

1) Observe Preparation for Test, see 22.

Diagnosis – Diagnostic Trouble Code (DTC) Memory (CF)

Preparation for Test:


1. Fuses ok,
2. Ignition: **ON**
3. Connect the Hand-Held Tester (HHT) to X11/4, according to diagram, see section 0.
4. Voltage supply to control modules and CAN data lines ok. See DM, B&A, Vol. 2, section 7.1, 23
5. All CAN data lines must be connected properly.



The diagnostic trouble codes (DTC's) can only be read out and erased **using the Hand-Held Tester (HHT)**.


DTC's for one particular system may be stored in other control modules, therefore readout the DTC's from all other relevant control modules as well. When reading out DTC's, all stored DTCs will appear, which means that some of the DTCs that appear, will not be relevant to the system being checked. Non-relevant DTCs will be described in the particular system.

Special Tools



965 589 00 01 00

Hand-Held-Tester



965 589 00 40 00

Test cable

Note regarding DTCs

Only those DTCs as noted in 12, are relevant for the convenience feature system.

Current diagnostic trouble codes are highlighted in black on the display. Additional detailed fault information based on fault type is displayed with nearly all diagnostic codes (DTC's) such as:

> Ω resistance too great

< Ω resistance too low

Γ1+ short circuit to positive (POS)

Γ1- short circuit to ground (GND)

-// open circuit

With some fault codes, additional information as well as fault frequency can be read out.


Fault frequency

Faults are noted by frequency of occurrence, i.e.: 4 periodic faults, 4 occurrences.

5.4 Convenience Feature (CF)


Models 202, 208, 210 as of M.Y. 1998

Diagnosis – Diagnostic Trouble Code (DTC) Memory (CF)

DTC 	Possible cause	Test step/Remedy ¹⁾
B1000	Roof control panel control module (N70) defective.	N70
B1001	Switch illumination, circuit 58d Γ1 (short circuit)	Wiring.
B1004	Lower control field control module (N72) does not belong to this model	Check vehicle coding, N72
B1010	Low voltage	See DM, B&A, Vol. 2, section 7.1, 23
B1011	Excessive voltage	See DM, B&A, Vol. 2, section 7.1, 23
B1013	Voltage supply, circuit 15R is missing from circuit 15	See DM, B&A, Vol. 2, section 7.1, 23
B1118	Sliding/pop-up roof switch (N70s1) signal time > 25 seconds or wiring Γ1 (short circuit)	Wiring, N70
B1520 001	Relay for sliding/pop-up roof (M12/1) does not switch over	N70
B1520 002	Relay signal time for sliding/pop-up roof (M12/1) is > 25 seconds	N70


¹⁾ Observe Preparation for Test, see 22.

Diagnosis – Diagnostic Trouble Code (DTC) Memory (CF)


DTC 	Possible cause	Test step/Remedy ¹⁾
B1520 003	Voltage supply for Hall sensors for sliding/pop-up roof motor (M12/1m1)	23 ⇒ 19.0
B1520 004	Hall sensors for sliding/pop-up roof motor (M12/1m1) have wrong direction of rotation	M12/1
B1520 005	Hall sensor 1 for sliding/pop-up roof motor (M12/1b1) defective	23 ⇒ 19.0 M12/1
B1520 006	Hall sensor 2 for sliding/pop-up roof motor (M12/1b2) defective	23 ⇒ 19.0 M12/1
B1000	Lower control field control module (N72) defective.	N72
B1004	Lower control field control module (N72) incorrect	Check vehicle coding, N72
B1010	Low voltage	See DM, B&A, Vol. 2, section 7.1, 23
B1011	Excessive voltage	See DM, B&A, Vol. 2, section 7.1, 23

1) Observe Preparation for Test, see 22.

Diagnosis – Diagnostic Trouble Code (DTC) Memory (CF)

DTC 	Possible cause	Test step/Remedy ¹⁾
B1120	<p>Left front power window switch (N72s1) signal time > 25 seconds or wiring Γ1 (short circuit) All except Model 208.4.</p> <p>On model 208.4, switch (S21/1) is installed in place of switch N72s1. S21/1 is connected to the Roll bar/power soft top control module (N52). Read DTC's out of Roll bar/power soft top control module.</p>	<p>N72</p> <p>N52</p>
B1121	<p>Right front power window switch (N72s1) signal time > 25 seconds or wiring Γ1 (short circuit)</p> <p>On model 208.4, switch (S21/1) is installed in place of switch N72s1. S21/1 is connected to the Roll bar/power soft top control module (N52). Read DTC's out of Roll bar/power soft top control module.</p>	<p>N72</p> <p>N52</p>
B1122	<p>Left rear power window switch (N72s3) signal time > 25 seconds or wiring Γ1 (short circuit)</p>	<p>N72</p>
B1123	<p>Right rear power window switch (N72s4) signal time > 25 seconds or wiring Γ1 (short circuit)</p>	<p>N72</p>
B1000	<p>Front driver-side door control module (N69/1) defective.</p>	<p>N69/1</p>


1) Observe Preparation for Test, see 22.

2) (only )

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Diagnosis – Diagnostic Trouble Code (DTC) Memory (CF)


DTC 	Possible cause	Test step/Remedy ¹⁾
B1010	Low voltage	See DM, B&A, Vol. 2, section 7.1, 23
B1011	Excessive voltage	See DM, B&A, Vol. 2, section 7.1, 23
B1100	Left front door lock switch (S86/1s1) ²⁾ (CF) unlock signal time > 25 seconds or wiring Γ1 (short circuit)	23 ⇒ 22.0, 23.0
B1101	Left front door lock switch (S86/1s2) ²⁾ (CF) lock signal time > 25 seconds or wiring Γ1 (short circuit)	23 ⇒ 22.0, 23.0
B1520 001	Relay for left front power window motor (M10/3) does not switch over	N69/1
B1520 002	Relay signal time for left front power window motor (M10/3) is > 25 seconds	N69/1
B1520 003	Voltage supply for Hall sensors for left front power window motor (M10/3) or wiring Γ1 (short circuit)	23 ⇒ 6.0 23 ⇒ 7.0

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998


Diagnosis – Diagnostic Trouble Code (DTC) Memory (CF)

DTC 	Possible cause	Test step/Remedy ¹⁾
B1520 004	Hall sensors for left front power window motor (M10/3) have wrong direction of rotation	M10/3
B1520 005	Hall sensor 1 for left front power window motor (M10/3) defective	Wiring, M10/3
B1520 006	Hall sensor 2 for left front power window motor (M10/3) defective	Wiring, M10/3
B1520 007	Left front power window motor (M10/3) current draw	Check M10/3 for possible binding, M10/3
B1000	Front passenger-side door control module (N69/2) defective.	N69/2
B1010	Low voltage	See DM, B&A, Vol. 2, section 7.1, 23
B1011	Excessive voltage	See DM, B&A, Vol. 2, section 7.1, 23
B1100	Right front door lock switch (S87/1s1) ²⁾ (CF) unlock signal time > 25 seconds or wiring ⌈ (short circuit)	23 ⇒ 22.0, 23.0

1) Observe Preparation for Test, see 22.

2) (only )

Diagnosis – Diagnostic Trouble Code (DTC) Memory (CF)


DTC 	Possible cause	Test step/Remedy ¹⁾
B1101	Right front door lock switch (S87/1s2) ²⁾ (CF) lock signal time > 25 seconds or wiring Γ1 (short circuit)	23 ⇒ 22.0, 23.0
B1520 001	Relay for right front power window motor (M10/4) does not switch over	N69/2
B1520 002	Relay signal time for right front power window motor (M10/4) is > 25 seconds	N69/2
B1520 003	Voltage supply for Hall sensors for right front power window motor (M10/4) or wiring Γ1 (short circuit)	23 ⇒ 11.0 23 ⇒ 12.0
B1520 004	Hall sensors for right front power window motor (M10/4) have wrong direction of rotation	M10/4
B1520 005	Hall sensor 1 for right front power window motor (M10/4) defective	Wiring, M10/4
B1520 006	Hall sensor 2 for right front power window motor (M10/4) defective	Wiring, M10/4

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998


Diagnosis – Diagnostic Trouble Code (DTC) Memory (CF)

DTC 	Possible cause	Test step/Remedy ¹⁾
B1520 007	Right front power window motor (M10/4) current draw	Check M10/3 for possible binding, M10/4
B1000	Rear driver-side door control module (N69/3) defective.	N69/3
B1010	Low voltage	See DM, B&A, Vol. 2, section 7.1, 23
B1011	Excessive voltage	See DM, B&A, Vol. 2, section 7.1, 23
B1155	Left rear power window switch (S21/3) signal time > 25 seconds or wiring ΓΓ– (short circuit to ground)	23 ⇒ 15.0
B1407 006	Short circuit between rear driver-side door control module (N69/3) and left rear power window switch (S21/3), Illumination for left rear power window switch (S21/3), End stage for rear driver-side door control module (N69/3).	Wiring. S21/3 N69/3
B1520 001	Relay for left rear power window motor (N69/3m1) does not switch over	N69/3
B1520 002	Relay signal time for left rear power window motor (N69/3m1) is > 25 seconds	N69/3

1) Observe Preparation for Test, see 22.


2) (only )

Diagnosis – Diagnostic Trouble Code (DTC) Memory (CF)


DTC 	Possible cause	Test step/Remedy ¹⁾
B1520 003	Voltage supply for Hall sensors for left rear power window motor (N69/3m1) or wiring Γ1 (short circuit)	N69/3
B1520 004	Hall sensors for left rear power window motor (N69/3m1) have wrong direction of rotation	N69/3
B1520 005	Hall sensor 1 for left rear power window motor (N69/3m1) defective	N69/3
B1520 006	Hall sensor 2 for left rear power window motor (N69/3m1) defective	N69/3
B1000	Rear passenger-side door control module (N69/4) defective.	N69/4
B1010	Low voltage	See DM, B&A, Vol. 2, section 7.1, 23
B1011	Excessive voltage	See DM, B&A, Vol. 2, section 7.1, 23
B1155	Right rear power window switch (S21/4) signal time > 25 seconds or wiring Γ1- (short circuit to ground)	23 ⇒ 17.0

¹⁾ Observe Preparation for Test, see 22.

Diagnosis – Diagnostic Trouble Code (DTC) Memory (CF)

DTC 	Possible cause	Test step/Remedy ¹⁾
B1407 006	Short circuit between rear passenger-side door control module (N69/4) and right rear power window switch (S21/4), Illumination for right rear power window switch (S21/4), End stage for rear passenger-side door control module (N69/4).	Wiring, S21/4 N69/4
B1520 001	Relay for right rear power window motor (N69/4m1) does not switch over	N69/4
B1520 002	Relay signal time for right rear power window motor (N69/4m1) is > 25 seconds	N69/4
B1520 003	Voltage supply for Hall sensors for right rear power window motor (N69/4m1) or wiring Γ1 (short circuit)	N69/4
B1520 004	Hall sensors for right rear power window motor (N69/4m1) have wrong direction of rotation	N69/4
B1520 005	Hall sensor 1 for right rear power window motor (N69/4m1) defective	N69/4
B1520 006	Hall sensor 2 for right rear power window motor (N69/4m1) defective	N69/4

1) Observe Preparation for Test, see 22.

2) (only )

Diagnosis – Recalling Actual values with HHT

The following tests and activations are possible via the Hand-Held Tester.

Preparation for Test

1. Fuses ok,
2. Battery voltage > 11,
3. Connect the Hand-Held Tester (HHT) to X11/4, according to diagram, see section 0,
4. Voltage supply to the control modules and CAN data lines ok, see DM, B&A, section 7.1, 23,
5. All CAN data lines properly connected.



The actual values and activations of any system may be stored in numerous other control modules, therefore readout all actual values and activations from the control modules which are relevant to this system. When reading out the actual values, all stored in that control module will be shown.

CAUTION!

Erasing the Convenience Feature (CF) DTC memory, will also erase the DTC memory for the Combination Control Module (N10-1) and Mirror, steering column adjustment, heated mirrors (MSC).


Abbreviations:

OCP	Over-head control panel control module (N70)
EIS	Electronic ignition key
PW	Power window motor
PSE	PSE control module (A37), combined functions
DCM 1	Front driver-side door control module (N69/1)
DCM 2	Front passenger-side door control module (N69/2)
DCM 3	Rear driver-side door control module (N69/3)
DCM 4	Rear passenger-side door control module (N69/4)
LCP	Lower control panel control module (N72)
CL	Central locking

The above noted abbreviations are in the second column of the following actual values tables in **bold type** to advise of hints (regarding in which of the control modules the actual values or activations are stored).


Diagnosis – Recalling Actual Values with HHT

Special Tools



965 589 00 01 00

Hand-Held-Tester










965 589 00 40 00

Test cable

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Diagnosis – Recalling Actual Values with HHT






⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
1.0	DCM1 DCM2	Front driver/passenger-side door control module (N69/1, N69/2) Circuit 30			✓ F	N69/1, N69/2
2.0	DCM1 DCM2 DCM3 DCM4	Power window motor synchronized			YES NO	Synchronize power window motor.
3.0	OCP	Roof control panel control module (N70) Circuit 30			✓ F	N70
4.0	DAS Drive auth.	Electronic ignition lock control module (N73) Circuit 15R		Ignition switch: Position 1 ON OFF	ON OFF	N73
5.0	DAS Drive auth.	Circuit 15		Ignition switch: Position 2 ON OFF	ON OFF	N73
6.0	DCM1 CL	IR signal from transmitter key via left front door IR receiver (A26/1) to front driver-side door control module (N69/1)		Point the transmitter key at the left front door IR receiver (A26/1) and unlock vehicle.	✓ F	23 ⇒ 2.0 Transmitter key defective.

¹⁾ Observe Preparation for Test, see 22.


5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Diagnosis – Recalling Actual Values with HHT

⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
7.0	DCMI CL	Determining if transmitter key matches vehicle		Point the transmitter key at the left front door IR receiver (A26/1) and unlock vehicle.	YES NO	23 ⇒ 2.0 Transmitter key does not belong to this vehicle.
8.0	DCMI CL	IR convenience feature signal from transmitter key to front driver-side door control module (N69/1)		Point the transmitter key at the left front door IR receiver (A26/1) and unlock vehicle, while keeping the button depressed.	YES NO	Check batteries in the transmitter key, 23 ⇒ 2.0, Transmitter key defective.
9.0	DCMI CL	Ground signal from left front door lock switch (S86/1s1) ²⁾ (CF), unlock, to front driver-side door control module (N69/1)		Using the mechanical key ²⁾ , unlock vehicle and hold key in that position.	YES NO	23 ⇒ 22.0, 23.0
10.0	DCMI PLW	Activation of: Left front power window motor (M10/3) via front driver-side door control module (N69/1)		With RCL or mechanical key ²⁾ , unlock vehicle and hold in that position.	LOWER STOP	23 ⇒ 5.0, 6.0, 7.0














¹⁾ Observe Preparation for Test, see 22.

²⁾ (only )


5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Diagnosis – Recalling Actual Values with HHT

⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
11.0	 	IR signal from transmitter key via left front door IR receiver (A26/1) to front driver-side door control module (N69/1).		Point transmitter key at left front door IR receiver (A26/1) and lock vehicle	✓ F	Check batteries in the transmitter key, 23 ⇒ 2.0 Transmitter key defective.
12.0	 	Determining if transmitter key matches vehicle		Point the transmitter key at the left front door IR receiver (A26/1) and lock vehicle.	YES NO	23 ⇒ 2.0, Transmitter key does not belong to vehicle.
13.0	 	IR convenience signal from transmitter key to front driver-side door control module (N69/1).		Point the transmitter key at the left front door IR receiver (A26/1) and lock vehicle.	YES NO	Check batteries in the transmitter key, Transmitter key defective.
14.0	 	Ground signal from left front door lock switch (S86/1s1) ²⁾ (CF), unlock, to front driver-side door control module (N69/1)		Using the mechanical key ²⁾ , lock vehicle and hold key in that position.	YES NO	23 ⇒ 22.0, 23.0






¹⁾ Observe Preparation for Test, see 22.

²⁾ (only )


5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998






Diagnosis – Recalling Actual Values with HHT

⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
15.0	DCM1 PW	Activation of: Left front power window motor (M10/3) via front driver-side door control module (N69/1)		With RCL or mechanical key ²⁾ , lock vehicle and hold in that position.	UP STOP F	23 ⇒ 5.0, 7.0
16.0	DCM2 CL	IR signal from transmitter key via right front door IR receiver (A26/2) to front passenger-side door control module (N69/2).		Point the transmitter key at the right front door IR receiver (A26/2) and unlock vehicle.	✓ F	Check batteries in the transmitter key, 23 ⇒ 3.0, Transmitter key defective.
17.0	DCM2 CL	Determining if transmitter key matches vehicle		Point the transmitter key at the right front door IR receiver (A26/2) and unlock vehicle.	YES NO	23 ⇒ 3.0, Transmitter key does not belong to vehicle.
18.0	DCM CL	IR convenience signal from transmitter key to front passenger-side door control module (N69/2).		Point the transmitter key at the right front door IR receiver (A26/2) and unlock vehicle, keeping the button depressed.	YES NO	Check batteries in the transmitter key, Transmitter key defective.

¹⁾ Observe Preparation for Test, see 22.






²⁾ (only )

Diagnosis – Recalling Actual Values with HHT

⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
19.0	DCM2 PW	Activation of: Right front power window motor (M10/4) via front passenger-side door control module (N69/2)		With RCL, unlock passenger-side door and hold in that position.	DOWN STOP F	23 ⇒ 10.0, 12.0
20.0	DCM2 CL	IR signal from transmitter key via right front door IR receiver (A26/2) to front passenger-side door control module (N69/2).		Point the transmitter key at the right front door IR receiver (A26/2) and lock vehicle.	✓ F	Check batteries in the transmitter key, 23 ⇒ 3.0, Transmitter key defective.
21.0	DCM2 CL	Determining if transmitter key matches vehicle		Point the transmitter key at the right front door IR receiver (A26/2) and lock vehicle.	YES NO	23 ⇒ 3.0, Transmitter key does not belong to vehicle.
22.0	DCM CL	IR convenience signal from transmitter key to front passenger-side door control module (N69/2).		Point the transmitter key at the right front door IR receiver (A26/2) and lock vehicle.	YES NO	Check batteries in the transmitter key, Transmitter key defective.

1) Observe Preparation for Test, see 22.

Diagnosis – Recalling Actual Values with HHT

⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
23.0	DCM2 PW	Activation of: Right front power window motor (M10/4) via front passenger-side door control module (N69/2)		With RCL, lock passenger-side door and hold in that position.	UP STOP F	23 ⇒ 10.0, 12.0
24.0	DCM3 PW	Activation of: Left rear power window motor (N69/3m1)		With transmitter key or mechanical key ²⁾ lock driver-side door and hold in this position.	UP STOP F	Rear driver-side door control module (N69/3).
25.0	DCM3 PW	Activation of: Left rear power window motor (N69/3m1)		With transmitter key or mechanical key ²⁾ unlock driver-side door and hold in this position.	DOWN STOP NO	Rear driver-side door control module (N69/3).
26.0	DCM4 PW	Activation of: Right rear power window motor (N69/4m1)		With transmitter key or mechanical key ²⁾ lock driver-side door and hold in this position.	UP STOP F	Rear passenger-side door control module (N69/4).





1) Observe Preparation for Test, see 22.

2) (only )


5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Diagnosis – Recalling Actual Values with HHT

⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
27.0	DCM4 PW	Activation of: Right rear power window motor (N69/4m1)		With transmitter key or mechanical key ²⁾ unlock driver-side door and hold in this position.	DOWN STOP F	Rear passenger-side door control module (N69/4).
28.0	LCP	Left front power window switch (N72s1) (center)		Ignition: ON Switch (N72s1): Press back of switch: Press back of switch past first detent and hold: Switch not pressed: Press front of switch: Press front of switch past first detent and hold:	DOWN AUTO. DOWN □ UP AUTO. UP	Lower control panel control module (N72).
29.0	UVS PW	Activation of: Left rear power window motor (M10/5) Model 208.4 only		With transmitter key or mechanical key ²⁾ lock driver-side door and hold in this position.	DOWN	CAN-data bus Lower control panel control module (N72). Roll bar/power soft top control module (N52).





¹⁾ Observe Preparation for Test, see 22.

²⁾ (only )

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Diagnosis – Recalling Actual Values with HHT





⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
30.0	LCP	Right front power window switch (N72s2) (center)		Ignition: ON Switch (N72s2): Press back of switch: Press back of switch past first detent and hold: Switch not pressed: Press front of switch past first detent and hold:	DOWN AUTO. DOWN □ AUTO. UP	Lower control panel control module (N72).
31.0	UVS PW	Activation of: Right rear power window motor (M10/6) Model 208.4 only		With transmitter key or mechanical key ²⁾ lock driver-side door and hold in this position.	DOWN	CAN-data bus Lower control panel control Roll bar/power soft top control module (N52).
32.0	UVS	CAN-signal from LCP to Roll bar /soft top control module (N52) for left rear window motor. Model 208.4 only		Ignition: ON Switch (N72s3): Press back of switch: Switch not pressed: Press front of switch:	DOWN □ UP	CAN data bus Lower control panel control module (N72)

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Diagnosis – Recalling Actual Values with HHT






⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
33.0	LVS	CAN-signal from LCP to Roll bar /soft top control module (N52) for right rear window motor. Model 208.4 only		Ignition: ON Switch (N72s4): Press back of switch: Switch not pressed: Press front of switch:	DOWN □ UP	CAN-data bus Lower control panel control module (N72)
34.0	LCP	Left rear power window switch (N72s3)		Ignition: ON Switch (N72s3): Press back of switch: Press back of switchpast first detent and hold: Switch not pressed: Press front of switch: Press front of switch past first detent and hold:	DOWN AUTO. DOWN □ UP AUTO. UP	Lower control panel control module (N72).
35.0	LCP	Right rear power window switch (N72s4)		Ignition: ON Switch (N72s4): Press back of switch: Press back of switchpast first detent and hold: Switch not pressed: Press front of switch: Press front of switch past first detent and hold:	DOWN AUTO. DOWN □ UP AUTO. UP	Lower control panel control module (N72).

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Diagnosis – Recalling Actual Values with HHT





⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
36.0		Left rear power window switch (S21/3)		Ignition: ON Switch (S21/3): Press back of switch: DOWN Press back of switch past first detent and hold: AUTO. DOWN Switch not pressed: □ Press front of switch: UP Press front of switch past first detent and hold: AUTO. UP		23 ⇒ 15.0
37.0		Right rear power window switch (S21/4)		Ignition: ON Switch (S21/4): Press back of switch: DOWN Press back of switch past first detent and hold: AUTO. DOWN Switch not pressed: □ Press front of switch: UP Press front of switch past first detent and hold: AUTO. UP		23 ⇒ 17.0

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Diagnosis – Recalling Actual Values with HHT





⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
38.0	LCP	Child safety lock switch (N72s5)		Ignition: ON N72s5: Push switch to right (child symbol visible): Push switch to left (child symbol not visible):	LOCKED UNLOCKED	Lower control panel control module (N72).
39.0	LCP	Switch illumination Intensity circuit 58d Model 208.4 only: Switches N72s3, N72s4		Ignition: ON Lights: ON Based on dimming of interior.	□ - 100%	N72
40.0	DCM3 DCM4	Activation of: Illumination of rear door switches		Ignition: ON Intensity set to max. Test button pressed on HHT:	Switch illumination. F2: ON F3: OFF	Left rear power window switch (S21/3), Right rear power window switch (S21/4), Rear driver-side door control module (N69/3), Rear passenger-side door control module (N69/4).

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Diagnosis – Recalling Actual Values with HHT




⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
41.0	OCP	Roof control panel control module (N70) Circuit 30			✓ F	N70
42.0	OCP	Vehicle recognized			YES NO	Check version codes in electronic ignition switch control module (N73), N70
43.0	OCP	Sliding/pop-up roof (SR) switch (N70s1)		Ignition: ON SR switch (N70s1): Press back of switch: Switch not pressed: Press front of switch: Push switch up : Pull switch down :	SR OPENS □ CLOSES POP-UP ROOF "UP" CLOSES	N70

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Diagnosis – Recalling Actual Values with HHT






⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
44.0	OCP	Sliding/pop-up roof Position test		Ignition: ON Open pop-up roof Open pop-up roof to end stop Open sliding roof Open sliding roof to end position	SLIDING ROOF CLOSED POP-UP ROOF OPEN POP-UP ROOF END POSITION SLIDING ROOF OPEN SLIDING ROOF END POSITION	⇒ 44.0
45.0	OCP	Sliding/pop-up roof synchronization		Ignition: ON Sliding/pop-up roof synchronized	YES NO	Synchronize sliding/pop-up roof by raising pop-up roof completely and then keep switch pressed for more then 1 second. ⇒ 42.0

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Diagnosis – Recalling Actual Values with HHT


⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/remedy ¹⁾
46.0	OCP	Sliding/pop-up roof Anti-flutter position (Model 210 Wagon only)		Sliding/pop-up roof closed Press sliding/pop-up roof (SR) switch (N70s1) back until sliding/pop-up roof stops (SR will not fully open).	Anti-flutter position attained. YES NO	Version coding of electronic ignition switch control module (N73), Sliding/pop-up roof (M12/10 motor).
47.0	OCP	Sliding/pop-up roof (M12/1) motor Hall sensors (values count)		Ignition: ON Switch (N70s1): Pushed backwards : Pressed forwards : Push switch upwards : Pull switch down :	Sliding roof opens, values increase. Sliding roof closes, values decrease.	Sliding/pop-up roof (M12/1) motor
48.0	PSE	Door contact switch		<10 V >10 V	YES NO	DM, B&A, Vol. 1, section 3.4, 23
49.0	PSE	Door contact switch		<15.5 V >15.5 V	YES NO	DM, B&A, Vol. 1, section 3.4, 23

¹⁾ Observe Preparation for Test, see 22.

Diagnosis – Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy ¹⁾
No. 1 Convenience Opening Central unlocking of windows/sliding/pop-up roof with RCL or electronic vehicle key ²⁾ does not function	Door switches (S17/3, S17/4, S17/5, S17/6) Left/right front door IR receivers (A26/1, A26/2) Front driver/passenger-side door control modules (N69/1, N69/2) Electronic ignition switch control module (N73) PSE control module (A37)	DM, B&A, Vol. 1, section 3.4, 23, 23 ⇒ 2.0 – 4.0
No. 2 Convenience Closing Central locking of windows/sliding/pop-up roof with RCL or electronic vehicle key ²⁾ does not function	Door switches (S17/3, S17/4, S17/5, S17/6) Left/right front door IR receivers (A26/1, A26/2) Front driver/passenger-side door control modules (N69/1, N69/2) Electronic ignition switch control module (N73) PSE control module (A37)	DM, B&A, Vol. 1, section 3.4, 23, 23 ⇒ 2.0 – 4.0
No. 3 Safety Opening	Door switches (S17/3, S17/4, S17/5, S17/6) Left/right front door IR receivers (A26/1, A26/2) Front driver/passenger-side door control modules (N69/1, N69/2) Electronic ignition switch control module (N73) PSE control module (A37)	DM, B&A, Vol. 1, section 3.4, 23, 23 ⇒ 2.0 – 4.0
No. 4 All windows do not function Model 208.4 only	Roll Bar control module/power soft top control module (N52) CAN data bus to N52	N52 DM, B&A, Vol. 3, section 11.3, 23,

1) Observe Preparation for Test, see 22.

2) (only )

Diagnosis – Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy ¹⁾
No. 5 Model 208.4 only Left front power window does not function.	Window not synchronized Left front power window switch (S21/1) in middle console Roll Bar control module/Soft top control module (N52) CAN data bus to N52 Front driver door control module (N69/1) Left front power window motor (M10/3)	23 ⇒ 5.0 23 ⇒ 6.0 23 ⇒ 8.0
No. 6 Left front power window opening does not function	Left front power window switch (N72s1) Left front power window motor (M10/3) Front driver-side door control module (N69/1)	13 ⇒ 28.0 23 ⇒ 5.0 23 ⇒ 5.0
No. 7 Left front power window one-touch opening does not function	Windows not synchronized. Left front power window switch (N72s1) Left front power window motor (M10/3) Front driver-side door control module (N69/1)	Synchronize window, 13 ⇒ 28.0 23 ⇒ 5.0, 6.0, 7.0 23 ⇒ 5.0
No. 8 Left front power window closing does not function.	Left front power window switch (N72s1) Left front power window motor (M10/3) Front driver-side door control module (N69/1)	13 ⇒ 28.0 23 ⇒ 5.0 23 ⇒ 5.0
No. 9 Left front power window one-touch closing does not function.	Window not synchronized Left front power window switch (N72s1) Left front power window motor (M10/3) Front driver-side door control module (N69/1)	Synchronize window, 13 ⇒ 28.0 23 ⇒ 5.0, 6.0, 7.0 23 ⇒ 5.0

¹⁾ Observe Preparation for Test, see 22.

Diagnosis – Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy ¹⁾
No. 10 Model 208.4 only Right front power window does not function.	Window not synchronized Right front power window switch (S21/2) in middle console Roll Bar control module/power soft top control module (N52) CAN data bus to N52 Front passenger-side door control module (N69/2) Right front power window motor (M10/4)	23 ⇒ 13.0 23 ⇒ 10.0 23 ⇒ 11.0
No. 11 Right front power window opening does not function.	Right front power window switch (N72s2) Right front power window motor (M10/4) Front passenger-side door control module (N69/2)	13 ⇒ 30.0 23 ⇒ 10.0 23 ⇒ 11.0
No. 12 Right front power window one-touch opening does not function.	Window not synchronized Right front power window switch (N72s2) Right front power window motor (M10/4) Front passenger-side door control module (N69/2)	Synchronize window, 13 ⇒ 30.0 23 ⇒ 10.0, 11.0, 12.0 23 ⇒ 11.0
No. 13 Right front power window closing does not function	Right front power window switch (N72s2) Right front power window motor (M10/4) Front passenger-side door control module (N69/2)	13 ⇒ 30.0 23 ⇒ 10.0 23 ⇒ 10.0
No. 14 Right front power window one-touch closing does not function.	Window not synchronized Right front power window switch (N72s2) Right front power window motor (M10/4) Front passenger-side door control module (N69/2)	Synchronize window, 13 ⇒ 30.0 23 ⇒ 10.0, 11.0, 12.0 23 ⇒ 10.0

1) Observe Preparation for Test, see 22.

Diagnosis – Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy ¹⁾
No. 15 Model 208.4 only Left rear power window does not function.	Wiring Left rear power window switch (N72s3) Lower control field control module (N72) Roll Bar control module/power soft top control module (N52) CAN data bus to N52 Left rear power window motor (M10/5)	13 ⇒ 29.0 23 ⇒ 14.0 N52 DM, B&A, Vol. 3, section 11.3, 23,
No. 16 Left rear power window opening with switches (N72s3, S21/3) does not function.	Left rear power window switch (N72s3) Left rear power window switch (S21/3) Rear driver-side door control module (N69/3)	13 ⇒ 34.0 13 ⇒ 36.0 N69/3
No. 17 Left rear power window opening with switches (N72s3, S21/3) does not function (one-touch opening).	Window not synchronized, Left rear power window switch (N72s3) Left rear power window switch (S21/3) Rear driver-side door control module (N69/3)	Synchronize window, 13 ⇒ 34.0 13 ⇒ 36.0 N69/3
No. 18 Left rear power window closing with switches (N72s3, S21/3) does not function.	Left rear power window switch (N72s3) Left rear power window switch (S21/3) Rear driver-side door control module (N69/3)	13 ⇒ 34.0 13 ⇒ 36.0 N69/3
No. 19 Left rear power window closing with switches (N72s3, S21/3) does not function (one-touch closing).	Window not synchronized, Left rear power window switch (N72s3) Left rear power window switch (S21/3) Rear driver-side door control module (N69/3)	Synchronize window, 13 ⇒ 34.0 13 ⇒ 36.0 N69/3

1) Observe Preparation for Test, see 22.

Diagnosis – Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy ¹⁾
No. 20 Model 208.4 only Right rear power window does not function	Wiring Right rear power window switch (N72s4) Lower control field control module (N72) Roll Bar control module/power soft top control module (N52) CAN data bus to N52 Right rear power window motor (M10/6)	13 ⇒ 33.0 23 ⇒ 16.0 DM, B&A, Vol. 3, section 11.3, 23,
No. 21 Right rear power window opening with switches (N72s4, S21/4) does not function.	Left rear power window switch (N72s4) Left rear power window switch (S21/4) Rear driver-side door control module (N69/4)	13 ⇒ 35.0 13 ⇒ 37.0 N69/4
No. 22 Right rear power window opening with switches (N72s4, S21/4) does not function (one-touch opening).	Window not synchronized, Left rear power window switch (N72s4) Left rear power window switch (S21/4) Rear driver-side door control module (N69/4)	Synchronize window, 13 ⇒ 35.0 13 ⇒ 37.0 N69/4
No. 23 Right rear power window closing with switches (N72s4, S21/4) does not function.	Left rear power window switch (N72s4) Left rear power window switch (S21/4) Rear driver-side door control module (N69/4)	13 ⇒ 35.0 13 ⇒ 37.0 N69/4

¹⁾ Observe Preparation for Test, see 22.

Diagnosis – Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy ¹⁾
No. 24 Right rear power window closing with switches (N72s4, S21/4) does not function (one-touch closing).	Window not synchronized, Left rear power window switch (N72s4) Left rear power window switch (S21/4) Rear driver-side door control module (N69/4)	Synchronize window, 13 ⇒ 35.0 13 ⇒ 37.0 N69/4
No. 25 Child safety lock-out for left rear or right rear door does not function.	Child safety lock switch (N72s5)	13 ⇒ 38.0
No. 26 Window does not close completely. Model 208.4 only Front windows do not close completely	Faulty synchronization.	Using the HHT, (control module adaption, synchronization) desynchronize window, and then via window switch close window (to stop) and then hold window switch for more then 1 second.
No. 27 Window goes out of synchronization frequently.	Interrupted voltage supply (circuit 30) for door control module. Hall sensors Version coding in electronic ignition switch control module (N73) incorrect.	See HHT-control module adaption, Synchronization Procedure.

1) Observe Preparation for Test, see 22.

Diagnosis – Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy ¹⁾
No. 28 Sliding/pop-up roof does not function.	Voltage supply for roof control panel control module (N70).	13 ⇒ 41.0
No. 29 Sliding roof opening does not function.	Sliding/pop-up roof (SR) switch (N70s1) Sliding/pop-up roof (M12/1) motor	13 ⇒ 43.0 13 ⇒ 44.0, 46.0, 47.0
No. 30 Sliding roof closing does not function.	Sliding/pop-up roof (SR) switch (N70s1) Sliding/pop-up roof (M12/1) motor	13 ⇒ 43.0 13 ⇒ 44.0, 47.0
No. 31 Pop-up roof opening does not function.	Sliding/pop-up roof (SR) switch (N70s1) Sliding/pop-up roof (M12/1) motor	13 ⇒ 43.0 13 ⇒ 44.0, 47.0
No. 32 Pop-up roof closing does not function.	Sliding/pop-up roof (SR) switch (N70s1) Sliding/pop-up roof (M12/1) motor	13 ⇒ 43.0 13 ⇒ 44.0, 47.0

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Electrical Test Program – Component Locations (CF)

Model 210 shown




Figure 1

- M10/3 Left front power window motor
- M10/4 Right front power window motor
- M12/1 Sliding/pop-up roof
- N69/1 Front driver-side door control module
- N69/2 Front passenger-side door control module
- N69/3 Rear driver-side door control module
- N69/4 Rear passenger-side door control module
- N70 Roof control panel control module
- N70s1 Sliding/pop-up roof (SR) switch
- N72 Lower control field control module
- S21/3 Left rear power window switch
- S21/4 Right rear power window switch

P72.29-0234-57

Electrical Test Program – Component Locations (CF)

Model 208 shown




Figure 2

- M10/3 Left front power window motor
- M10/4 Right front power window motor
- M12/1 Sliding/pop-up roof
- N69/1 Front driver-side door control module
- N69/2 Front passenger-side door control module
- N70 Roof control panel control module
- N70s1 Sliding/pop-up roof (SR) switch
- N72 Lower control field control module

P72.29-0242-57

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Electrical Test Program – Component Locations (CF)

Model 208.4 shown




Figure 3

- M10/3 Left front power window motor
- M10/4 Right front power window motor
- M10/5 Left rear power window motor
- M10/6 Right rear power window motor
- N52 Roll bar control module/soft top control module
- N69/1 Front driver-side door control module
- N69/2 Front passenger-side door control module
- N70 Roof control panel control module
- N72 Lower control field control module
- N72s3 Left rear power window switch
- N72s4 Right rear power window switch
- S21/1 Left front power window switch in middle console
- S21/2 Right front power window switch in middle console

P72.29-2010-06

Electrical Test Program – Component Locations (CF)

Model 210 shown




Figure 4

- S86/1 Left front door lock switch (CF) (only USA J)
- S87/1 Right front door lock switch (CF) (only J)
- S88/2 Trunk lid lock switch (CF) (only USA J)
- X11/4 Data link connector (DTC readout)

P72.29-0235-57

5.4 Convenience Feature (CF)


Models 202, 208, 210 as of M.Y. 1998

Electrical Test Program – Connection of Components (CF)

Driver-side (USA) (J)
(Models 202, 210 shown)

Figure 1

A26/1	Left front door IR receiver
A37	PSE control module
CAN	Control-Area-Network
M10/3	Left front power window motor
M10/4	Right front power window motor
M12/1	Sliding/pop-up roof
N69/1	Front driver-side door control module
N69/2	Front passenger-side door control module
N69/3	Rear driver-side door control module
N69/4	Rear passenger-side door control module
N70	Roof control panel control module
N73	Electronic ignition switch control module
S17/3	Left front door switch
S17/4	Right front door switch
S17/5	Left rear door switch
S17/6	Right rear door switch
S86/1	Left front door lock switch (CF)
S88/2	Trunk lid lock switch (CF)
1	Electronic vehicle key




P82.40-0230-57

Electrical Test Program – Connection of Components (CF)

Passenger-side/right hand drive (USA) (J)
(Models 202, 210 shown)

Figure 2


- A26/2 Right front door IR receiver
- A37 PSE control module
- CAN Control-Area-Network
- M10/3 Left front power window motor
- M10/4 Right front power window motor
- M12/1 Sliding/pop-up roof
- N69/1 Front driver-side door control module
- N69/2 Front passenger-side door control module
- N69/3 Rear driver-side door control module
- N69/4 Rear passenger-side door control module
- N70 Roof control panel control module
- N73 Electronic ignition switch control module
- S17/3 Left front door switch
- S17/4 Rightfront door switch
- S17/5 Left rear door switch
- S17/6 Right rear door switch
- S87/1 Right front door lock switch (CF)
- S88/2 Trunk lid lock switch (CF)
- 1 Electronic vehicle key



P82.40-0227-57

Electrical Test Program – Connection of Components (CF)

Driver-side (USA) (J)
(Model 208 shown)




P82.40-0234-06

Figure 3

- A26/1 Left front door IR receiver
- A37 PSE control module
- CAN Control-Area-Network
- M10/3 Left front power window motor
- M10/4 Right front power window motor
- M12/1 Sliding/pop-up roof
- N69/1 Front driver-side door control module
- N69/2 Front passenger-side door control module
- N70 Roof control panel control module
- N73 Electronic ignition switch control module
- S17/3 Left front door switch
- S17/4 Right front door switch
- 1 Electronic vehicle key

Electrical Test Program – Connection of Components (CF)

Passenger-side (USA) (J)
(Model 208 shown)



P82.40-0235-06

Figure 4

- A26/2 Right front door IR receiver
- A37 PSE control module
- CAN Control-Area-Network
- M10/3 Left front power window motor
- M10/4 Right front power window motor
- M12/1 Sliding/pop-up roof
- N69/1 Front driver-side door control module
- N69/2 Front passenger-side door control module
- N70 Roof control panel control module
- N73 Electronic ignition switch control module
- S17/3 Left front door switch
- S17/4 Rightfront door switch
- 1 Electronic vehicle key

Electrical Test Program – Connection of Components (CF)

Driver-side (USA) (J)
(Model 208.4 shown)





Figure 5

- A37 PSE control module
- CAN Control-Area-Network
- M10/3 Left front power window motor
- M10/4 Right front power window motor
- M10/5 Left rear power window motor
- M10/6 Right rear power window motor
- N52 Roll bar control module/soft top control module
- N69/1 Front driver-side door control module
- N69/2 Front passenger-side door control module
- N70 Roof control panel control module
- N73 Electronic ignition switch control module
- S17/3 Left front door switch
- S17/4 Rightfront door switch
- S86/1 Left front door lock switch (CF)
- S88/2 Trunk lid lock switch (CF)
- 1 Electronic vehicle key

P72.29-2012-06

Electrical Test Program – Connection of Components (CF)



P77.20-0270-53

Figure 6

- CAN Control-Area-Network
- M12/1 Sliding/pop-up roof
- N70 Roof control panel control module
- N70s1 Sliding/pop-up roof (SR) switch

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Electrical Test Program – Connection of Components (CF)

Models 202, 210 shown





Figure 7

- CAN Control-Area-Network
- M10/3 Left front power window motor
- M10/4 Right front power window motor
- N69/1 Front driver-side door control module
- N69/2 Front passenger-side door control module
- N69/3 Rear driver-side door control module
- N69/4 Rear passenger-side door control module
- N72 Lower control field control module
- N72s1 Left front power window switch
- N72s2 Right front power window switch
- N72s3 Left rear power window switch
- N72s4 Right rear power window switch
- N72s5 Child safety lock switch
- S21/3 Left rear power window switch
- S21/4 Right rear power window switch

P72.29-0241-57

Electrical Test Program – Connection of Components (CF)

Model 208 shown



P72.29-0243-57

Figure 8

- CAN Control-Area-Network
- M10/3 Left front power window motor
- M10/4 Right front power window motor
- N69/1 Front driver-side door control module
- N69/2 Front passenger-side door control module
- N72 Lower control field control module
- N72s1 Left front power window switch
- N72s2 Right front power window switch

Electrical Test Program – Preparation for Test

Preliminary work:

Diagnosis - Diagnostic Trouble Code (DTC) Memory 12

Preparation for Test

1. Battery voltage > 11 V,
2. Fuses ok,
3. Disconnect battery ground cable prior to connecting or disconnecting any electrical connector to any control module (to prevent the storing of erroneous diagnostic trouble codes),
4. HHT Module: "Component Connections",
5. Voltage supply to all the following control modules:
 - Circuit 15R from electronic ignition switch control module (N73)
 - Electronic ignition switch control module (N73)
 - Lower control field control module (N72)
 - Front driver-side door control module (N69/1)
 - Front passenger-side door control module (N69/2)
 - Rear driver-side door control module (N69/3)
 - Rear passenger-side door control module (N69/4) and
6. All CAN data lines ok, see DM, B&A, vol. 2, section 7.1, 23
7. Model 208.4 only:
 - Switch middle console (S21/1) is installed instead of switch N72s1.
 - S21/1 is connected to the Roll bar/power soft top control module (N52).

Electrical wiring diagrams:

Electrical Troubleshooting Manual, Model 202, group 72, 77, 82
 Model 208, group 72, 77, 82
 Model 210, group 72, 77, 82



Observe version coding for:

Front driver-side door control module (N69/1)
 Front passenger-side door control module (N69/2)
 Electronic ignition switch control module (N73)

For test measuring purposes, the CAN connection to the following control modules must be connected:


PSE control module (A37)
 Signal pickup-and activation module (SAM) (N10/1)

Model 208

Synchronization of the windows is only possible with the doors **closed**.

Electrical Test Program – Preparation for Test

Special Tools



Electrical connecting set

Conventional tools, test equipment










Description	Brand, model, etc.
Multimeter ¹⁾	Fluke models 23, 83, 85, 87

¹⁾ Available through the MBUSA Standard Equipment Program.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Electrical Test Program – Test




⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy ¹⁾
1.0		Door switches (S17/3, S17/4, S17/5, S17/6)				DM, B&A, vol. 1, 3.4, PSE, 23
2.0		Left front door IR receiver (A26/1) Voltage supply	4 —  (3)  N69/1 — 14 (3)	Disconnect connector (3) from front driver-side door control module (N69/1).	4.5 – 5.5 V	⇒ 2.1, N69/1
2.1		Left front door IR receiver (A26/1)	1 —   A26/1 — 2	Remove A26/1	4.5 – 5.5 V	Wiring.
3.0		Right front door IR receiver (A26/2) Voltage supply	4 —  (3)  N69/2 — 14 (3)	Disconnect connector (3) from front passenger-side door control module (N69/2).	4.5 – 5.5 V	⇒ 3.1, N69/2
3.1		Right front door IR receiver (A26/2)	2 —   A26/2 — 3	Remove A26/2	4.5 – 5.5 V	Wiring.

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)




Models 202, 208, 210 as of M.Y. 1998

Electrical Test Program – Test

⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy ¹⁾
4.0	B1120	Left front power window switch (N72s1)		Ignition: ON Switch (N72s1): Press back of switch: Press back of switch past first detent and hold: Press front of switch: Press front of switch past first detent and hold:	 DOWN AUTO. DOWN UP AUTO. UP	Lower control field control module (N72).
5.0	B1520	Activation of: Left front power window motor (M10/3) via front driver-side door control module (N69/I)	2 —(—  — 5	Disconnect connector from M10/3. Ignition: ON Switch (N72s1): Press back of switch: Press back of switch past first detent and hold: Press front of switch: Press front of switch past first detent and hold:	Relay in control module N69/1 engages audibly. For approx. 1 second: 11 – 14 V 11 – 14 V –11 to –14 V –11 to –14 V	Wiring, ⇒ 4.0, N69/1

¹⁾ Observe Preparation for Test, see 22.

Electrical Test Program – Test





⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy ¹⁾
6.0	81520	Left front power window motor (M10/3) Voltage supply Hall sensor		Ignition: ON Disconnect connector from M10/3	11 – 14 V	Wiring, Front driver-side door control module (N69/I).
7.0	81520	Left front power window motor (M10/3) Hall sensor		Ignition: ON Switch (N72s1): Press back of switch: Press back of switch past first detent and hold: Press front of switch: Press front of switch past first detent and hold:	Window opens, raising values. Window closes, falling values.	Hall sensor

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Electrical Test Program – Test



⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy ¹⁾
8.0		Left front power window switch (S21/1) Model 208.4 only		Ignition: ON Switch (S21/1) in position: □ DOWN AUTO. DOWN UP AUTO. UP	approx. 14 V approx. 8.5 V approx. 0 V approx. 5 V approx. 2.5 V	If one value is not OK, S21/1, If several values are not OK, ⇒ 8.1 All values are OK, ⇒ 8.2
8.1		Resistance Model 208.4 only		Ignition: OFF Disconnect connector from N52, Switch (S21/1) in position: □ DOWN AUTO. DOWN UP AUTO. UP	> 20 kΩ approx. 900 Ω approx. 0 Ω approx. 510 Ω approx. 125 Ω	If one value is not OK, S21/1, If several values are not OK, Wiring, S21/1, All values are OK, N52
8.2		Switch illumination Model 208.4 only		Disconnect connector from S21/1, Light switch S1 (58d) ON ; Set combination display (A1) at max setting	approx. 11 V	Wiring, S21/1

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)




Models 202, 208, 210 as of M.Y. 1998

Electrical Test Program – Test

⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy ¹⁾
9.0	B1121	Right front power window switch (N72s2)		Ignition: ON Switch (N72s2): Press back of switch: Press back of switch past first detent and hold: Press front of switch: Press front of switch past first detent and hold:	 DOWN AUTO. DOWN UP AUTO. UP	Lower control field control module (N72).
10.0	B1520	Activation of: Right front power window motor (M10/4) via front passenger-side door control module (N69/2)	2 — (← ⊖ ⊕ →) — 5 M10/4	Disconnect connector from M10/4. Ignition: ON Switch (N72s2): Press back of switch: Press back of switch past, first detent and hold: Press front of switch: Press front of switch past first detent and hold:	Relay in control module N69/2 engages audibly. For approx. 1 second: 11 – 14 V 11 – 14 V –11 to –14 V –11 to –14 V	Wiring, ⇒ 8.0, N69/2

¹⁾ Observe Preparation for Test, see 22.

Electrical Test Program – Test





⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy ¹⁾
11.0	81520	Right front power window motor (M10/4) Voltage supply Hall sensor	3 —(—  —) 6	Ignition: ON Disconnect connector from M10/4	11 – 14 V	Wiring, N69/2
12.0	81520	Right front power window motor (M10/4) Hall sensor		Ignition: ON Switch (N72s2): Press back of switch: Press back of switch past first detent and hold: Press front of switch: Press front of switch past first detent and hold:	Window opens, raising values. Window closes, falling values.	Hall sensor

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Electrical Test Program – Test




⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy ¹⁾
13.0		Right front power window switch (S21/2) Model 208.4 only		Ignition: ON Switch (S21/2) in position: □ DOWN AUTO, DOWN UP AUTO, UP	11 – 14 V approx. 14 V approx. 8.5 V approx. 0 V approx. 5 V approx. 2.5 V	If one value is not OK, S21/2, If several values are not OK, ⇒ 13.1 All values are OK, ⇒ 13.2
13.1		Resistance Model 208.4 only		Ignition: OFF Disconnect connector from N52 Switch (S21/2) in position: □ DOWN AUTO, DOWN UP AUTO, UP	> 20 kΩ approx. 900 Ω approx. 0 Ω approx. 510 Ω approx. 125 Ω	If one value is not OK, S21/2, If several values are not OK, Wiring, S21/2 All values are OK, N52
13.2		Switch illumination Model 208.4 only		Disconnect connector from S21/2 Light switch S1 (58d) ON; Set combination display (A1) at max setting	approx. 11 V	Wiring, S21/2

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)




Models 202, 208, 210 as of M.Y. 1998

Electrical Test Program – Test

⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy ¹⁾
14.0	B1122	Left rear power window switch (N72s3)		Ignition: ON Switch (N72s3): Press back of switch: Press back of switch past first detent and hold: Press front of switch: Press front of switch past first detent and hold:	DOWN AUTO. DOWN UP AUTO. UP	Lower control field control module (N72).
15.0	B1155 B1407	Left rear power window switch (S21/3)	2 — () — 7	Ignition: OFF Switch (S21/3): Press back of switch: Press back of switch past first detent and hold: Press front of switch: Press front of switch past first detent and hold:	1240 Ω 330 Ω 510 Ω 660 Ω	Wiring, S21/3

¹⁾ Observe Preparation for Test, see 22.

Electrical Test Program – Test





⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy ¹⁾
16.0	B1123	Right rear power window switch (N72s4)		Ignition: ON Switch (N72s4): Press back of switch: Press back of switch past first detent and hold: Press front of switch: Press front of switch past first detent and hold:	DOWN AUTO. DOWN UP AUTO. UP	Lower control field control module (N72).
17.0	B1155 B1407	Right rear power window switch (S21/4)	2 —  — 7	Ignition: OFF Switch (S21/4): Press back of switch: Press back of switch past first detent and hold: Press front of switch: Press front of switch past first detent and hold:	1240 Ω 330 Ω 510 Ω 660 Ω	Wiring, S21/4

1) Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Electrical Test Program – Test










⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy ¹⁾
18.0		Child safety lock switch (N72s5)		Ignition: ON Switch (N72s5): Push switch to right: (Child symbol visible) Push switch to left: (Child symbol not visible)	LOCKED UNLOCKED	Lower control field control module (N72).
19.0	B1520	Sliding/pop-up roof motor (M12/1m1) Hall sensors		Ignition: ON Press sliding/pop-up roof (SR) switch (N70s1): Press switch forward : Press switch backward :	Sliding roof closes, raising values. Sliding roof opens, falling values.	⇒20.0
20.0	B1520	Sliding/pop-up roof motor (M12/1m1) Voltage supply Hall sensor	6 —(—  —) 4 (B) (B)	Disconnect connector (B) from N70 Ignition: ON	11 – 14 V	Roof control panel control module (N70).

¹⁾ Observe Preparation for Test, see 22.

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Electrical Test Program – Test

⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy ¹⁾
21.0		Sliding/pop-up roof (SR) switch (N70s1)		Ignition: ON Switch (N70s1): Press switch backward : Press switch forward : Push switch up : Pull switch down :	OPENING CLOSING OPENING CLOSING	Roof control panel control module (N70).
22.0		Voltage supply from front driver-side door control module (N69/1) to left front door lock switch (CF) (S86/1)²⁾	N69/1 1 —  + (2)  +		11 – 14 V	Front driver-side door control module (N69/1).
23.0	 	Left front door lock switch (CF) (S86/1)²⁾	N69/1 2 —  + (2)  — 3 (2)	With key in left front door lock: Lock: Rest position: Unlock:	<1 Ω >20 kΩ <1 Ω	Wiring, S86/1



1) Observe Preparation for Test, see 22.

2) (only  )

5.4 Convenience Feature (CF)

Models 202, 208, 210 as of M.Y. 1998

Electrical Test Program – Test



⇒		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy ¹⁾
25.0		Non-USA vehicles only, continue to next test step.				
25.0		Non-USA vehicles only, continue to next test step.				
26.0		Trunk lid lock switch (CF) (S88/2)		With key in trunk lid lock: Lock: Rest position: Unlock:	<1 Ω >20 kΩ <1 Ω	Wiring, S88/2

¹⁾ Observe Preparation for Test, see 22.

Version Coding

Version coding must be undertaken when a new front driver-side door control module (N69/1) and/or front passenger-side door control module (N69/2) are connected to battery current for the first time.

Coding

-  
- Rest of the world

Coding Accessories

- Electrical Seat Adjustment (ESA) YES/NO



The front driver-side door control module (N69/1) and/or front passenger-side door control module (N69/2) may be version coded as many times as necessary.