4.10 Models 129, 140, 170 as of M.Y. 1998

	Page
Diagnosis	
Function Test	11/1
Diagnostic Trouble Code (DTC) Memory	12/1
Recalling Actual Values with HHT	13/1
Activation	14/1
Electrical Test Program	
Component Locations	20/1
Connection of Components	21/1
Preparation for Test	22/1
Test	23/1
Hand-Held Tester (HHT)	
Version Coding and Programming	31/1

Components

- Radio frequency DAS control module (N54/3) (model 170 only)
- DAS radio frequency/infrared control module (N54/4) (models 129, 140)
- Transmitter key and mechanical key with transponder
- Transponder coil (L11) (located on the steering lock)
- Left/right front door IR receiver (A26/1, A26/2) (models 129, 140)
- Left front door lock switch (CF) (S86/1) USA
- Trunk lid lock switch (CF) (S88/2) USA

i

Radio frequency DAS control module (N54/3) or DAS radio frequency/infrared control module (N54/4)

The following functions **a)** and **b)** are carriered out with the above noted control modules:

i

D = ===

a) Radio frequency/infrared remote central locking

- Evaluation of the radio signal.
- Evaluation of the infrared signal, (models 129 and 140)
- Activation of
- Central locking (CL)
- Remote trunk release (RTR) (models 129, 140)
- Anti-theft Alarm (ATA)
- Comfort feature (models 129, 140)
- Verification signal via turn signal system, models 129, 140: via combination relay module (N10/2), model 170 via locking confirmation relay module (K54).
- (USA) Recognition and evaluation of the mechanical locking nut switch.



b) Drive Authorization System (DAS)

- Activation of the coil for the transponder in the steering lock.
- Recognition and evaluation of the transponder signal.
- With a valid transponder code, the release of the engine control module via CAN.



The drive authorization is independent from the infrared remote control and the battery condition in the transmitter key. The requirement is that the transponder in the transmitter key supplies the proper data via the transponder coil (L11) to the radio frequency DAS control module (N54/3), or DAS radio frequency/infrared control module (N54/4). If the data is recognized as correct, then a start signal is given.

C/2



If the transponder is invalid or the energy can not be produced for the transponder coil, the release of the engine control module is not granted. This is indicated via the "Start Error" indicator lamp in the instrument cluster, which is in turn activated via the engine control module. Locking of the engine control module is accomplished via the Radio frequency DAS control module (N54/3) or DAS radio frequency/infrared control module (N54/4). These control modules are connected to the engine control module via CAN data bus. After locking the engine control module (ignition key has been removed from the ignition switch), the engine control module renders the fuel injection system inoperative.



Radio frequency DAS control module (N54/3) or DAS radio frequency/infrared control module (N54/4) and the engine control module are "married" to each other via an identification code exchange. For this reason, the identification codes can not be erased. Thus, it is not possible to swap control modules between vehicles for testing purposes.

Actual Values

Via the Hand-Held Tester (HHT) up to 8 different transponders can be tested for locking approval. Additionally, the synchronization of the individual transmitter keys can be tested. The HHT can also indicate the current, last used transmitter key. Additionally, an indication is given if the version coding is locked, which means, that after 250 activations (circuit 15 ON), the Radio frequency DAS control module (N54/3) or DAS radio frequency/infrared control module (N54/4) are "married" and it is then possible to perform only limited version coding changes. The readout of the actual values is menu driven.

Revocable and Irrevocable Deactivation

Tranmitter keys can be **revocably** deactivated. This is accomplished via the HHT and is menu driven for individual transmitter keys. Via the HHT, revocably deactivated transmitter keys can be reactivated. Both the transponder and transmitter functions are deactivated or activated together. Transmitter keys can be **irrevocably** deactivated (**only upon the customer's consent**). This is accomplished via the HHT and is menu driven. The reactivation of the irrevocably deactivated tranmitter key is not possible. The radio and infrared function as well as the transponder function have been deactivated.

Version Coding

When replacing the radio frequency DAS control module (N54/3) or DAS radio frequency/infrared control module (N54/4), version coding must be performed via the HHT. Upon entry into the actual values menu, the control module number on which the version coding has been performed before is given automatically.

The version coding is menu driven.



The radio frequency DAS control module (N54/3) or DAS radio frequency/infrared control module (N54/4) and the engine control module are "married" to each other via an identification code exchange. For this reason, the identification codes can not be erased and this code remains with the vehicle for the rest of its service life. Only the mechanical locks can be replaced.

C/3



If the customer loses an IR transmitter key (which includes a mechanical key):

The vehicle's RCL identification code remains, the lost IR transmitter key (s) is made invalid via blocking. To maintain vehicle security, all mechanical locks should be replaced using a new mechanical lock number code. You must notify your facing PDC of any mechanical lock changes, by using the Lock Change Notice Form.

If the RCL control module is defective:

A new Radio frequency DAS control module (N54/3) or DAS radio frequency/infrared control module (N54/4) must be specially ordered for the specific vehicle, using the same RCL identification code as the previously installed control module.

If a mechanical lock or key is defective:

Replace the mechanical lock or key with a new one, using the same mechanical lock code number (special order from your facing PDC).

Preliminary work: Check operation of central locking;

Check batteries in infrared transmitter key,

see SMS, Job No. 80–420

Models 129, 140 (Model 140 shown)




Figure 1

P80.35-0206-05

Model 170




Figure 2

P80.35-0205-05

Preparation for Test:

- 1. Battery voltage 11 14 V,
- 2. Fuses ok,
- 3. Central locking system in proper operating condition.
- 4. Batteries in transmitter key ok,
- 5. Transmitter signals are synchronized,
- 6. Transmitter key removed from electronic ignition switch,
- 7. Side windows lowered approx. 100 mm (4 in.),
- 8. All doors and trunk lid closed,
- 9. Central locking system is unlocked,
- 10. Activation of the blinker system has not been cancelled via the HHT.

i

The locking and unlocking function is indicated via the turn signal system.

Blinker mode: Locking: 3x

Unlocking 1x

Blinkfrequency: 1.5hz

Activation of the blinker system as noted above can be cancelled via the HHT via the version coding menu, upon customer request.

Activation of the hazard flasher system will cancel the verification signal sent via the turn signal system.

Test st	ep/Test scope	Test condition	Nominal value	Possible cause/Remedy 1)
⇒ 1.0	Locking of vehicle with transmitter key (radio signal) via radio antenna.	Do not point transmitter key towards any of the IR receivers. Lock vehicle using transmitter key (radio signal).	Vehicle is locked. Blinker system blinks 3X.	$13,$ $23 \Rightarrow 1.0,$ $23 \Rightarrow 2.0,$ $23 \Rightarrow 3.0,$ $23 \Rightarrow 4.0,$ $23 \Rightarrow 5.0,$ $23 \Rightarrow 10.0,$ $23 \Rightarrow 10.0,$ $23 \Rightarrow 21.0,$ Version coding incorrect.
⇒ 2.0	Unlocking of vehicle with transmitter key (radio signal) via radio antenna.	Do not point transmitter key towards any of the IR receivers. Unlock vehicle using transmitter key (radio signal).	Vehicle is unlocked. Blinker system blinks 1X.	13, 14, 23 \Rightarrow 1.0, 23 \Rightarrow 2.0, 23 \Rightarrow 3.0, 23 \Rightarrow 4.0, 23 \Rightarrow 5.0, 23 \Rightarrow 11.0, 23 \Rightarrow 17.0, 23 \Rightarrow 18.0, 23 \Rightarrow 19.0, Version coding incorrect.

¹⁾ Observe Preparation for Test, see 22.

Test st	ep/Test scope	Test condition	Nominal value	Possible cause/Remedy 1)
⇒ 3.0	Locking of vehicle via left front door IR receiver (A26/1) Model 129/140 only	Open side windows. Point transmitter key towards left front door IR receiver (A26/1). Lock vehicle by pressing lock button on transmitter key for > 1 second and hold.	Vehicle is locked. Blinker system blinks 3X. Side windows close.	13, 14, 23 \Rightarrow 1.0, 23 \Rightarrow 2.0, 23 \Rightarrow 6.0, 23 \Rightarrow 7.0, 23 \Rightarrow 10.0, 23 \Rightarrow 16.0, 23 \Rightarrow 20.0, 23 \Rightarrow 21.0, Version coding incorrect.
⇒ 4.0	Unlocking of vehicle via left front door IR receiver (A26/1) Model 129/140 only	Close side windows. Point transmitter key towards left front door IR receiver (A26/1). Unlock vehicle by pressing unlock button on transmitter key for > 1 second and hold.	Vehicle is unlocked. Blinker system blinks 1X. Side windows open (model 129 only).	13, 14, 23 \Rightarrow 1.0, 23 \Rightarrow 2.0, 23 \Rightarrow 6.0, 23 \Rightarrow 7.0, 23 \Rightarrow 11.0, 23 \Rightarrow 17.0, 23 \Rightarrow 18.0, 23 \Rightarrow 19.0, Version coding incorrect.

¹⁾ Observe Preparation for Test, see 22.

Test st	ep/Test scope	Test condition	Nominal value	Possible cause/Remedy 1)
⇒ 5.0	Locking of vehicle via right front door IR receiver (A26/2) Model 129/140 only	Open side windows. Point transmitter key towards right front door IR receiver (A26/2). Lock vehicle by pressing lock button on transmitter key for > 1 second and hold.	Vehicle is locked. Blinker system blinks 3X. Side windows close.	13, 14, 23 \Rightarrow 1.0, 23 \Rightarrow 2.0, 23 \Rightarrow 8.0, 23 \Rightarrow 9.0, 23 \Rightarrow 10.0, 23 \Rightarrow 16.0, 23 \Rightarrow 20.0, 23 \Rightarrow 21.0, Version coding incorrect.
⇒ 6.0	Unlocking of vehicle via right front door IR receiver (A26/2) Model 129/140 only	Close side windows. Point transmitter key towards right front door IR receiver (A26/2). Unlock vehicle by pressing unlock button on transmitter key for > 1 second and hold.	Vehicle is unlocked. Blinker system blinks 1X. Side windows open (model 129 only).	13, 14, 23 \Rightarrow 1.0, 23 \Rightarrow 2.0, 23 \Rightarrow 8.0, 23 \Rightarrow 9.0, 23 \Rightarrow 11.0, 23 \Rightarrow 17.0, 23 \Rightarrow 18.0, 23 \Rightarrow 19.0, Version coding incorrect.

Observe Preparation for Test, see 22.

Test step/Test scope		Test condition	Nominal value	Possible cause/Remedy 1)
⇒ 7.0	Locking of vehicle with a mechanical lock cylinder. (USA) J only	Lock vehicle using mechanical key via a mechanical lock cylinder.	Vehicle is locked.	13, $23 \Rightarrow 1.0$, $23 \Rightarrow 2.0$, $23 \Rightarrow 14.0$, $23 \Rightarrow 16.0$, $23 \Rightarrow 20.0$, $23 \Rightarrow 21.0$, Version coding incorrect.
⇒ 8.0	3	Unlock vehicle using mechanical key via a mechanical lock cylinder.	Vehicle is unlocked.	13, $23 \Rightarrow 1.0$, $23 \Rightarrow 2.0$, $23 \Rightarrow 6.0$, $23 \Rightarrow 15.0$, $23 \Rightarrow 17.0$, $23 \Rightarrow 18.0$, $23 \Rightarrow 19.0$, Version coding incorrect.

¹⁾ Observe Preparation for Test, see 22.

Test step/Test scope	Test condition	Nominal value	Possible cause/Remedy 1)
⇒ 9.0 Open trunk lid with transmitter key Model 129/140	Trunk lid lock key slot is not in 90° (key can be removed) position. Press unlock trunk lid button on transmitter key.	Trunk lid opens. Retractable trunk lid grip (RTG) extends (model 140 only).	13, 14, 23 \Rightarrow 1.0, 23 \Rightarrow 2.0, 23 \Rightarrow 3.0, 23 \Rightarrow 4.0, 23 \Rightarrow 5.0, 23 \Rightarrow 8.0, 23 \Rightarrow 17.0, 23 \Rightarrow 18.0, 23 \Rightarrow 19.0, Version coding incorrect, Electrical/pneumatic fault in PSE, RTG has mechanical fault.
⇒ 10.0 Activate engine management.	Insert transmitter key and turn key to right to stop in steering column lock.	Engine starts.	$23 \Rightarrow 1.0,$ $23 \Rightarrow 2.0,$ $23 \Rightarrow 22.0,$ $23 \Rightarrow 23.0,$ $23 \Rightarrow 24.0,$ $23 \Rightarrow 25.0,$ $23 \Rightarrow 26.0,$ $23 \Rightarrow 27.0,$ $23 \Rightarrow 28.0,$ $23 \Rightarrow 29.0,$ $23 \Rightarrow 30.0,$ DTC memory, engine, Actual values, engine.

¹⁾ Observe Preparation for Test, see 22.

Preliminary work:	
Function test	11

Preparation for Test (DTC readout):

- 1. Fuses OK.
- 2. Battery voltage >11 V.
- 3. Vehicle is unlocked via RCL,
- 4. Ignition: **ON**
- 5. Connect Hand-Held Tester (HHT) according to connection diagram shown in section 0.


i


The diagnostic trouble codes (DTC's) can only be read out and erased using the Hand-Held Tester (HHT).

Current diagnostic trouble codes are highlighted in black on the display. Additional detailed fault information based on fault type is displayed with nearly all diagnostic codes (DTC's) such as:

- $> \Omega$ Resistance too great
- $< \Omega$ Resistance too low
- Γ1– Short circuit to ground (GND)
- Γ1+ Short circuit to positive (POS)
- -//- Open circuit

Special Tools





Hand-Held-Tester

Test cable

DTC	Possible cause	Hints	Test step/Remedy 1)
81000	Radio frequency DAS control module (N54/3) or DAS radio frequency/infrared control module (N54/4)		Replace N54/3 or N54/4
B1100	Control line deactivation, PSE/CL, CF, ATA Γ1+ or Γ1-, (SN1)		23⇒ 17.0 23⇒ 18.0 23⇒ 19.0
B1101	Control line activation, PSE/CL, CF, ATA Γ1+ or Γ1–, (SN2)		23⇒ 16.0 23⇒ 20.0 23⇒ 21.0
81105	Control line IR signal from left front door IR receiver (A26/1) ΓΊ–		23⇒ 7.0
B1103	Control line IR signal from right front door IR receiver (A26/2) ΓΊ–		23⇒ 9.0

¹⁾ Observe Preparation for Test, see 22.

DTC	Possible cause	Hints	Test step/Remedy 1)
וסרופ	Motor release via faulty release code (CAN)		12, $23 \Rightarrow 22.0$, $23 \Rightarrow 23.0$, $23 \Rightarrow 24.0$, $23 \Rightarrow 25.0$, $23 \Rightarrow 26.0$, $23 \Rightarrow 27.0$, $23 \Rightarrow 28.0$, $23 \Rightarrow 29.0$, $23 \Rightarrow 30.0$
B1702	Motor release for left cylinder bank via faulty release code (CAN)		12, $23 \Rightarrow 22.0$, $23 \Rightarrow 23.0$, $23 \Rightarrow 24.0$, $23 \Rightarrow 25.0$, $23 \Rightarrow 26.0$, $23 \Rightarrow 27.0$, $23 \Rightarrow 28.0$, $23 \Rightarrow 29.0$, $23 \Rightarrow 30.0$

¹⁾ Observe Preparation for Test, see 22.

DTC	Possible cause	Hints	Test step/Remedy 1)
81703	Invalid transponder		Transmitter key defective - replace, Erase DTC memory.
ВІЛОЧ	Transponder coil (L11) could not be charged		23⇒ 22.0, 23⇒ 23.0
B1706	Activation of locking confirmation relay module (N54) or combination relay module (N10/2) has		23⇒ 12.0, 23⇒ 13.0

¹⁾ Observe Preparation for Test, see 22.


Diagnosis – Recalling Actual Values with HHT


The following tests and activations are possible via the Hand-Held Tester.

Preparation for Test:

- 1. Fuses ok,
- 2. Battery voltage > 11,
- 3. Side windows open,
- 4. Ignition: ON
- 5. Connect the Hand-Held Tester (HHT) to X11/4, according to diagram, see section 0.
- 6. After the "Function" Menu in the HHT, the menu point 3 (actual values) appears.
- 7. The following tests are possible via the HHT (see 13/3).

Special Tools





Electrical Test Program – Test Actual Values

\Rightarrow	Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
1.0	Circuit 30			√ F	23 ⇒ 1.0
2.0	Status of radio/infrared remote central locking/unlocking		Using transmitter key: Lock vehicle: Unlock vehicle:	F	$23 \Rightarrow 3.0,$ $23 \Rightarrow 4.0,$ $23 \Rightarrow 5.0$
3.0	Recently used transmitter key (number of key listed)		Example (of key):	Key numbered:	Transmitter key.
4.0	Recently used transponder (number of transponder listed)		Example (of transponder):	Transponder numbered:	Transmitter key.
5.0	Country version			USA, Japan, balance of world countries	See 31/1

Electrical Test Program – Test Actual Values

\Rightarrow	Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
6.0	Lock switch circuit 1 (USA) only)		Insert key into driver's door or trunk lid lock and turn: To left detent: Release key:	l	23 ⇒ 14.0, 23 ⇒ 15.0
7.0	Lock switch circuit 2 (@A) only)		Insert key into driver's door or trunk lid lock and turn: To right detent: Release key:	Yes NO	23 ⇒ 14.0, 23 ⇒ 15.0
8.0	Transponder amplitude			20-30V	$23 \Rightarrow 22.0$, $23 \Rightarrow 23.0$, Transmitter key.
9.0	Transponder inserted in ignition switch		Insert transponder into ignition switch	√ F	Transmitter key invalid, Transponder invalid.
10.0	Versions within the version coding are locked			YES NO	Test counter for Circuit 15 ON has run out, Radio frequency DAS control module (N54/3), DAS radio frequency/infrared control module (N54/4).

Electrical Test Program – Test Actual Values

\Rightarrow	Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
11.0	Radio frequency transmitter key synchronized. (Actual value readout for all 8 transmitter keys is indeed possible)			YES NO	Transmitter key is deactivated, Re-synchronize transmitter keys. Radio frequency DAS control module (N54/3), DAS radio frequency/infrared control module (N54/4).
12.0	Transponder initialized (Actual value readout for all 8 transmitter keys is indeed possible)			YES NO	Transmitter key is deactivated, Radio frequency DAS control module (N54/3), DAS radio frequency/infrared control module (N54/4).
13.0	Transmitter key and transponder are activated (Actual value readout for all 8 transmitter keys is indeed possible)			Activated, Irrevocable deactivation Revocable deactivation	Perform activation or deactivation of the transmitter key, Radio frequency DAS control module (N54/3), DAS radio frequency/infrared control module (N54/4).

The following systems/signals can be activated via the HHT:

- Status of Radio frequency/Infrared Remote Central Locking (RCL).
- Convenience Feature (CF)
- Remote Trunk Release (RTR).
- Radio frequency signal.
- · Infrared signal.
- Activation of the turn signal system.

Preparation for Test:

- 1. Fuses ok,
- 2. Battery voltage > 11,
- 3. Side windows open,
- 4. Ignition: **ON**
- 5. After the "Function" Menu in the HHT, the menu point 4 (activation) appears.
- 6. The following tests are possible via the HHT (see 14/2).

\Rightarrow	Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
1.0	Status of Radio Frequency/Infrared Remote Central Locking (RCL)		Press F2 Press F3	Vehicle unlocks. Vehicle locks.	$23 \Rightarrow 16.0,$ $23 \Rightarrow 17.0,$ $23 \Rightarrow 18.0,$ $23 \Rightarrow 19.0,$ $23 \Rightarrow 20.0,$ $23 \Rightarrow 21.0$
2.0	Convenience Feature (CF) Opening Model 129 only		Press F2 Press F3	Side windows open. Function is interrupted.	$23 \Rightarrow 17.0,$ $23 \Rightarrow 18.0,$ $23 \Rightarrow 19.0$
3.0	Convenience Feature (CF) Closing Models 129/140		Press F2 Press F3	Side windows open and sliding pop-up roof closes.	$23 \Rightarrow 16.0,$ $23 \Rightarrow 20.0,$ $23 \Rightarrow 21.0$
4.0	Remote trunk release Models 129/140		Press F2	Trunk lid opens.	23 ⇒ 17.0, 23 ⇒ 18.0, 23 ⇒ 19.0, Electrical/pneumatic fault in PSE, Trunk lid lock has mechanical fault.

\Rightarrow	Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
5.0	Radio frequency signal received from transmitter key		Ignition: ON Press button on transmitter key.	YES (for approx. 2 seconds). NO	23 ⇒ 1.0, 23 ⇒ 2.0, 23 ⇒ 3.0, Transmitter key, Radio frequency DAS control module (N54/3), DAS radio frequency/infrared control module (N54/4).
6.0	IR signal received by left front door IR receiver (A26/1) Models 129/140 only		Ignition: ON Point second IR transmitter key at (A26/1) and press button.	YES (for approx. 2 seconds).	23 ⇒ 6.0, 23 ⇒ 7.0, Transmitter key, DAS radio frequency/infrared control module (N54/4).

\Rightarrow	Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
7.0	IR signal received by right front door IR receiver (A26/2) Models 129/140 only		Ignition: ON Point second IR transmitter key at (A26/2) and press button.	YES (for approx. 2 seconds). NO	23 ⇒ 8.0, 23 ⇒ 9.0, Transmitter key, DAS radio frequency/infrared control module (N54/4).
8.0	Activation of turn signal system		Press F2 Press F3	Turn signal system blinks 1x. Turn signal system blinks 3x.	23 ⇒ 10.0, 23 ⇒ 11.0, Version coding incorrect.

Electrical Test Program – Component Locations

Model 129 shown

Figure 1

A1 Instrument cluster
A26/1 Left front door IR receiver
A26/2 Right front door IR receiver
L11 Transponder coil

N3/4 Engine control module (HFM-SFI)

N10/2 Combination relay module (turn signal with trailier

coupling, rear window defroster, wiper motor,

ATA)

N54/4 DAS radio frequency/infrared control module


(located behind instrument cluster)

1 Transmitter key with transponder

2 Antenna

S86/1 Left front door lock switch (CF) USA
S87/1 Right front door lock switch (CF) USA

S88s1 ATA/CF microswitch USA



P80.30-0378-06

Electrical Test Program – Component Locations

Model 140 sedan with HFM-SFI shown

Figure 2

A1 Instrument cluster
A26/1 Left front door IR receiver
A26/2 Right front door IR receiver

L11 Transponder coil

N3/4 Engine control module (HFM-SFI)

N10/2 Combination relay module (turn signal with trailier

coupling, rear window defroster, wiper motor,

AIA)

N54/4 DAS radio frequency/infrared control module


(located behind instrument cluster)

1 Transmitter key with transponder

2 Antenna

S86/1 Left front door lock switch (CF) USA
S87/1 Right front door lock switch (CF) USA

S88/2 Trunk lid lock switch (CF) USA



P80.30-0379-06


Electrical Test Program – Component Locations

Model 170 with HFM-SFI shown

Figure 3

S88/2

Α1 Instrument cluster L11 Transponder coil K54 Locking confirmation relay module N3/4 Engine control module (HFM-SFI) Combination control module N10-3 N54/3 Radio frequency DAS control module (located behind instrument cluster) Transmitter key with transponder 2 Antenna Left front door lock switch (CF) USA S87/9 Trunk lid lock switch (CF) USA




P80.30-0380-06

Electrical Test Program – Connection of Components

Model 129

Figure 1

Α	Radio/Infrared remote control for central locking
В	Drive authorization stage (DAS)
	(release of motor management via transponder)
A1	Instrument cluster
A26/1	Left front door IR receiver
A26/2	Right front door IR receiver
A37	PSE control module, combined functions
CAN	Control-Area-Network
E3e1	Turn signal lamp
E4e1	Turn signal lamp
E6/1	Left turn signal/side marker lamp (USA)
E6/2	Right turn signal/side marker lamp USA
L11	Transponder coil
N10/2	Combination relay module (turn signal with trailier coupling, rear window defroster, wiper motor, ATA)
N54/4	DAS radio frequency/infrared control module
S2/1	Ignition/starter switch
S86/1	Left front door lock switch (CF) USA
S87/1	Right front door lock switch (CF) USA
S88s1	ATA/CF microswitch USA
X11/4	Data link connector (DTC readout)
1	Transmitter key with transponder
2	Antenna
3	Engine control module



P80.30-0442-06

Engine


Electrical Test Program – Connection of Components

Model 140 sedan shown

Figure 2

3

Α Radio/Infrared remote control for central locking В Drive authorization stage (DAS) (release of motor management via transponder) Α1 Instrument cluster A26/1 Left front door IR receiver A26/2 Right front door IR receiver A37 PSE control module, combined functions CAN Control-Area-Network E3e1 Turn signal lamp E4e1 Turn signal lamp Left turn signal/side marker lamp USA E6/1 Right turn signal/side marker lamp USA E6/2 L11 Transponder coil N10/2 Combination relay module (turn signal with trailier coupling, rear window defroster, wiper motor, ATA) N54/4 DAS radio frequency/infrared control module S2/1 Ignition/starter switch Left front door lock switch (CF) (USA) S86/1 Right front door lock switch (CF) USA S87/1 Trunk lid lock switch (CF) USA S88/2 Transmitter key Antenna



P80.30-0383-06

Engine control module


Engine

Electrical Test Program – Connection of Components

Model 170

Figure 3

A B	Radio/Infrared remote control for central locking Drive authorization stage (DAS) (release of motor management via transponder)
A1	Instrument cluster
A37	PSE control module, combined functions
CAN	Control-Area-Network
E3e1	Turn signal lamp
E4e1	Turn signal lamp
E6/1	Left turn signal/side marker lamp (USA)
E6/2	Right turn signal/side marker lamp USA
L11	Transponder coil
K54	Locking confirmation relay module
N10-3	combination control module
N54/3	Radio frequency/infrared control module
S2/1	Ignition/starter switch
S87/9	Left front door lock switch (CF) USA
S88/2	Trunk lid lock switch (CF) USA
X11/4	Data link connector (DTC readout)
1	Transmitter key with transponder
2	Antenna
3	Engine control module



P80.30-0381-06

Engine

Electrical Test Program – Preparation for Test

Preliminary work:	
Diagnosis - Diagnostic Trouble Code (DTC) Memory	 12

Preparation for Test:

- 1. Fuses OK.
- 2. Battery voltage >11 V.
- 3. Install model specific HHT module into HHT.
- 4. Connect the Hand-Held Tester (HHT) to X11/4, according to diagram, see section 0.

Electrical wiring diagrams:

Electrical Troubleshooting Manual, Model 129, Volume 2, group 80,


Model 140, Volume 2, group 80,


Model 170, Volume 2, group 80

Electrical Test Program – Preparation for Test

Special Tools







Electrical connecting set

35-pin socket box

18-pin and 12-pin CAN test cable

Conventional tools, test equipment

Description	Brand, model, etc.
Multimeter 1)	Fluke models 23, 83, 85, 87, 88

¹⁾ Available through the MBUSA Standard Equipment Program.

Electrical Test Program – Preparation for Test

Connection Diagram - Socket Box



Location of Radio frequency DAS control module (N54/3) and DAS radio frequency/infrared control module (N54/4) is behind instrument cluster (A1), Model 170 shown

After reinstallation of the instrument cluster and the steering wheel, the DTC fault codes for the SRS Airbag are to be erased via the HHT.

Figure 1

001 Radio frequency DAS/DAS radio frequency


/IR DAS control module connector

002 Test cable (202 589 15 63 00) 003 Multimeter

004/050 Socket box (35-pole)

N54/3 Radio frequency DAS control module N54/4 DAS radio frequency/infrared control

module



Electrical Test Program – Test

\Rightarrow		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
1.0	01	Radio frequency DAS control module (N54/3) or DAS radio frequency/infrared control module (N54/4) Voltage supply Circuit 30		Ignition: ON	√ F	Wiring, Battery.
2.0		Radio frequency DAS control module (N54/3) or DAS radio frequency/infrared control module (N54/4) Voltage supply Circuit 15	N54/3 N54/4 	Ignition: OFF Ignition: ON	<1 V 11 – 14 V	Wiring, Circuit 31, ⇒ 2.1
2.1		Circuit 15	N54/4	Ignition: OFF Ignition: ON	<1 V 11 – 14 V	Wiring, Circuit 15

Electrical Test Program – Test

\Rightarrow	Test scope	Test conr	nection		Test condition	Nominal value	Possible cause/Remedy
3.0	Antenna HF line ΓΊ shield	20 — ((1.6)	N54/3 N54/4) — 21 (1.7)	Disconnect N54/3 or N54/4 from	>20 kΩ	Wiring.
4.0	Antenna HF line ΓΊ+	20 — ఁ (1.6)	N54/3 N54/4) — 32 (1.18)	Disconnect N54/3 or N54/4 from	>20 kΩ	Wiring.
5.0	Antenna HF line ΓΊ–	30 — ఁ (1.16)	N54/3 N54/4 -) — 20 (1.6)	Disconnect N54/3 or N54/4 from	>20 kΩ	Wiring.
6.0	Left front door IR receiver (A26/1) Voltage supply Models 129/140 only	28 — ((1.14)	N54/4) — 18 (1.18)		4.4 – 5.5 V	Wiring, 23 ⇒ 1.0, 23 ⇒ 2.0, N54/4

\Rightarrow		Test scope	Test conn	ection		Test condition	Nominal value	Possible cause/Remedy
6.1		A26/1 Voltage supply Model 140 Model 129		A26/1 (Ŷ) ⁺ - A26/1 (Ŷ) ⁺ -	→ 2	Remove A26/1	4.4 – 5.5 V	Wiring, 23 ⇒ 1.0, 23 ⇒ 2.0, N54/4
7.0	B1105	Left front door IR receiver (A26/1) IR signal control line Models 129/140 only	30 — ((1.16)	N54/4) — 19 (1.5)	Lock vehicle by point transmitter key at driver- side IR receiver, keep button pressed. Read value after locking sequence has completed. Release button, and then read second value.	Difference of values between button pressed and button released approx. 0.1 – 1.0 V (less then button released value).	Wiring, $23 \Rightarrow 6.0$, $23 \Rightarrow 7.1.0$, $23 \Rightarrow 7.2.0$, A26/1, Transmitter key.
7.1	81102	Left front door IR receiver (A26/1) IR signal control line Γ1 – Models 129/140 only	30 — ((1.16)	N54/4) — 19 (1.5)	Disconnect N54/4 from	>20 kΩ	Wiring.

\Rightarrow	Test scope	Test connection		Test condition	Nominal value	Possible cause/Remedy
7.2	Left front door IR receiver (A26/1) IR signal control line Γ1 + Models 129/140 only	32 — (1.18) N54/4 (1.18)) — 19	Disconnect N54/4 from Disconnect A26/1	>20 kΩ	Wiring.
8.0	Right front door IR receiver (A26/2) Voltage supply Models 129/140 only	N54/4 	> — 26 (1.12)		4.4 – 5.5 V	Wiring, 23 ⇒ 1.0, 23 ⇒ 2.0, N54/4
8.1	A26/2 Voltage supply Model 140 Model 129	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	> ─ 2 > ─ 7	Remove A26/2	4.4 – 5.5 V	Wiring, 23 ⇒ 1.0, 23 ⇒ 2.0, N54/4

\Rightarrow		Test scope	Test connection		Test condition	Nominal value	Possible cause/Remedy
9.0	B1103	Right front door IR receiver (A26/2) IR signal control line Models 129/140 only	N54/4 	> — 27 (1.13)	Lock vehicle by point transmitter key at passenger-side IR receiver, keep button pressed. Read value after locking sequence has completed. Release button, and then read second value.	Difference of values between button pressed and button released approx. 0.1 – 1.5 V (less then button released value).	Wiring, $23 \Rightarrow 8.0$, $23 \Rightarrow 9.1.0$, $23 \Rightarrow 9.2.0$, A26/2, Transmitter key.
9.1	ВШОЗ	Right front door IR receiver (A26/2) IR signal control line Γ1 – Models 129/140 only	N54/4) — 27 (1.13)	Disconnect N54/4 from	>20 kΩ	Wiring.
9.2		Right front door IR receiver (A26/2) IR signal control line Γ1 + Models 129/140 only	32 — ((1.18)) — 27 (1.13)	Disconnect N54/4 from Disconnect A26/2	>20 kΩ	Wiring.

\Rightarrow	Test scope	Test con	nection		Test condition	Nominal value	Possible cause/Remedy
10.0	Locking conformation relay module (K54) Activation Model 170 Combination relay module (N10/2) Activation of blinker system Locking Models 129/140	16 — (1.16) 16 — (1.2)	N54/3	→ 32 (1.18) → 32 (1.18)	Locking of the vehicle via RCL	11 – 14 V intermittent for approx. 2 seconds. 11 – 14 V For approx. 2 seconds.	Wiring, 23 ⇒ 12.0, 23 ⇒ 13.0, N54/3, N54/4
11.0	Locking conformation relay module (K54) Activation Model 170 Combination relay module (N10/2) Activation of blinker system Unlocking Models 129/140	16 — ((1.2)	N54/3 N54/4) — 32 (1.18)	Unlocking of the vehicle via RCL	11 – 14 V for approx. 0.5 seconds.	Wiring, 23 ⇒ 12.0, 23 ⇒ 13.0, N54/3, N54/4

\Rightarrow		Test scope	Test connection		Test condition	Nominal value	Possible cause/Remedy
12.0	B1706	Locking conformation relay module (K54) OR Combination relay module (N10/2) Activation Wiring	N54/3 N54/4) — 32 (1.18)	Disconnect N54/3 or N54/4 from	>20 kΩ	Wiring.
13.0	B1706	Locking conformation relay module (K54) OR Combination relay module (N10/2) Activation Wiring	N54/3 N54/4 IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII) — 32 (1.16)	Disconnect N54/3 or N54/4 from	>20 kΩ	Wiring.

\Rightarrow	Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
14.0	Lock nut switch (S86/1) Circuit (USA) only Models 129/140	N54/3 N54/4 			Wiring, S86/1
		N54/3 N54/4 	S86/1: Rest position: Press and hold lock:	<1 V	
	Model 129	N54/4 23 — (V + (1.9)	S86/1: Rest position: Press and hold lock:		

\Rightarrow	Test scope	Test con	nection		Test condition	Nominal value	Possible cause/Remedy
15.0	Lock nut switch (S86/1) and Trunk lid lock switch (S88/2) Circuit (USA) only Models 140/170	23 — ((1.9)	N54/3 N54/4 	> — 32 (1.18)	Disconnect N54/3 or N54/4 from		Wiring, S88/2
		22 — ((1.8)	N54/3 N54/4 	> — 32 (1.18)	S88/2: Rest position: Press and hold lock:	<1 V	
	Lock nut switch (S86/1) and ATA/CF microswitch (S88s1) circuit (USA) only Model 129	23 — ((1.9)	N54/4	> — 32 (1.18)	S88s1: Rest position: Press and hold lock:		Wiring, S88s1

\Rightarrow		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
16.0	BUOI	Radio frequency DAS control module (N54/3) OR DAS radio frequency/infrared control module (N54/4) Output activation (PSE/CL, CF, ATA)	N54/3 N54/4 30 — 15 (1.16) (1.1)	All doors closed and vehicle is unlocked. Lock vehicle using transmitter key.	<pre>11 - 14 V <1 V (approx. 0.5 seconds) Turn signal system blinks 3X, vehicle locks.</pre>	Wiring, 23 ⇒ 20.0, 23 ⇒ 21.0, N54/3, N54/4, PSE (A37), Model 170: Combination control module (N10-3)
17.0	81100	Radio frequency DAS control module (N54/3) OR DAS radio frequency/infrared control module (N54/4) Output deactivation (PSE/CL, CF, ATA)	_	All doors closed and vehicle is locked. Unlock vehicle using transmitter key.	11 – 14 V <1 V (approx. 0.5 seconds) Turn signal system blinks 1X, vehicle unlocks.	Wiring, 23 ⇒ 18.0, 23 ⇒ 19.0, N54/3, N54/4, PSE (A37), Model 170: Combination control module (N10-3)

\Rightarrow		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
18.0	B1100	Control line deactivation (PSE/CL, CF, ATA)	N54/3 N54/4 ∭∭∭ 32 — (→ □ (Ω) + → 2 (1.18) (1.11	Disconnect N54/3 or N54/4 from	>20 kΩ	Wiring.
19.0	B((00	Control line deactivation (PSE/CL, CF, ATA) □□	N54/3 N54/4 ∭∭∭ 30 — ← — ② + — 2 (1.16) (1.11	Disconnect N54/3 or N54/4 from	>20 kΩ	Wiring.

\Rightarrow		Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
20.0	BUDI	Control line activation (PSE/CL, CF, ATA)	N54/3 N54/4 	Disconnect N54/3 or N54/4 from	>20 kΩ	Wiring.
21.0	B1101	Control line activation (PSE/CL, CF, ATA) □□□□		Disconnect N54/3 or N54/4 from	>20 kΩ	Wiring.

\Rightarrow		Test scope	Test connection		Test condition	Nominal value	Possible cause/Remedy
22.0	B1704	Coil for transponder (L11) Activation	N54/3 N54/4 — f + (1) + (2) + (3)	N54/4	Disconnect connector 3 from N54/3 or N54/4 Ignition: ON	125 kHz for approx. 0.2 – 0.8 seconds. (measureable by Fluke 83, 88)	23 ⇒ 1.0, 23 ⇒ 2.0, N54/3, N54/4
23.0	ВІЛОЧ	Coil for transponder (L11) Resistance	L11 1—(——@+	L11) — 2	Disconnect connector 3 from N54/3 or N54/4 Ignition: ON	4 – 6 Ω	L11
24.0		CAN H/CAN L data line Motor electronics activation Γ 1 to each other	N54/3 N54/4 1 — (-_Q^+_ (2)	N54/3 N54/4) — 2	Disconnect connector 2 from N54/3 or N54/4 Disconnect engine control module.	>20 kΩ	Wiring.

\Rightarrow	Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
25.0	CAN L data line Motor electronics activation _//_	N54/3 N54/4 1 — (→ □Ω → □Ω → 2 (2)	Disconnect connector 2 from N54/3 or N54/4 Disconnect engine control module, see foot note.	>1 Ω	Wiring.
26.0	CAN H data line Motor electronics activation -//-	N54/3 N54/4 1 — (→ □ (Ω) → - (2)	Disconnect connector 2 from N54/3 or N54/4 Disconnect engine control module, see foot note.	>1 Ω	Wiring.
27.0	CAN L data line Motor electronics activation Γ1+	N54/3 N54/4 N54/4	module.	>20 kΩ	Wiring.
28.0	CAN H data line Motor electronics activation Γ1+	N54/3 N54/4 N54/4	module.	>20 kΩ	Wiring.

²⁾ Prior to testing, please see appropriate ETM to determine engine control module harness socket number.

\Rightarrow	Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
29.0	CAN L data line Motor electronics activation Γ Γ Γ Γ	N54/3 N: N54/4 1 - (- Q +)-	54/3 Disconnect connector 2 from N54/3 or N54/4 Disconnect engine control module.	>20 kΩ	Wiring.
30.0	CAN H data line Motor electronics activation Γ	N54/3 N N54/4 2 — (————————————————————————————————	Disconnect connector 2 from N54/3 or N54/4 Disconnect engine control module.	>20 kΩ	Wiring.

Version Coding

- Control modules which need to be version coded, the menu point 6
 appears in the HHT display. These control modules are to be version
 coded as necessary.
- The version coding is menu-driven.

Possible version coding

Version		
Vehicle version	129/140, 170	
Convenience feature via IR signals (settings with "locked" version codes can not be changed)	Activated/Deactivated	
Remote trunk release	Activated/Deactivated	
Locking confirmation signal via turn signal system	Activated/Deactivated	
Activation of turn signal system via	Locking conformation relay module (K54)/Combination relay module (N10/2)	
Drive authorization via transponder (settings with "locked" version codes can not be changed)	Activated/Deactivated	
Engine CAN adjustment (baudrate): IFI, DFI, HFM-SFI, ME-SFI	IFI, DFI, HFM-SFI as of HHT step 50, ME-SFI/HFM-SFI as of HHT step 49	
Motor electronics activation	HFM-SFI, IFI, DFI, ME1.0, ME2.0	
Radio frequency	Activated/Deactivated	

Continued on next page

Version Coding

Possible version coding (continued)

· cooling version county					
Version					
Key-in-Test	Activated/Deactivated				
Panic alarm	Activated/Deactivated				
Locking nut switch (settings with "locked" version codes can not be changed)	Activated/Deactivated				
Convenience feature activated via locking nut switch	Yes/No				
Unlocking via valid transponder	Yes/No				
Vehicle indentification number (only if the VIN has not been locked)	WDB				