Component Locations Up to M.Y. 1997


Note:

M.Y. 1996 only:

Right front door lock switch deleted.



S2/1 Ignition/starter switch S86/1 Left front door lock switch S871 Right front door lock switch S88/2 Trunk lid lock switch



P82-6157-57

Component Locations Up to M.Y. 1997 with RCL receiver (interior rear view mirror) (A26/7)




Figure 2

P80.30-0219-57

#### **Component Locations**

As of M.Y. 1997:


IR receivers added in left front door and trunk lid.

Left front door lock switch deleted.

Right front door lock switch added.



S2/1 Ignition/starter switchS871 Right front door lock switchS88/2 Trunk lid lock switch



P82-6156-57



## After performing the Function Test, erase any stored DTC's (see section 0).

Test step/Test scope		Test condition	Nominal value	Possible cause/Remedy 1)
⇒ 1.0	Activate ATA via left front door	<ul> <li>Open driver's window.</li> <li>Lock driver's door with key. (up to M.Y. 1997)</li> <li>After approximately 15 seconds open door from inside.</li> <li>Deactivate ATA.</li> </ul>	Alarm horn sounds, lights flash.	23 ⇒ 6.0
⇒ 2.0	Activate ATA via right front door	<ul> <li>Open passenger window.</li> <li>Lock passenger door with key. (as of M.Y. 1997)</li> <li>After approximately 15 seconds open door from inside.</li> <li>Deactivate ATA.</li> </ul>	Alarm horn sounds, lights flash.	23 ⇒ 6.0
⇒ 3.0	Activate ATA via left or right rear door	<ul> <li>Open rear passenger window.</li> <li>Lock driver's door with key. (up to M. Y. 1997)</li> <li>Lock passenger door with key. (as of M. Y. 1997)</li> <li>After approximately 15 seconds open rear door from inside.</li> <li>Deactivate ATA.</li> </ul>	Alarm horn sounds, lights flash.	23 ⇒ 5.0

<sup>1)</sup> Observe Preparation for Test, see 22.

Test step/Test scope	Test condition	Nominal value	Possible cause/Remedy 1)
⇒ 4.0 Activate ATA via engine hood	<ul> <li>Open driver's window.</li> <li>Lock driver's door with key. (up to M. Y. 1997)</li> <li>Lock passenger door with key. (as of M. Y. 1997)</li> <li>Wait approximately 15 seconds.</li> <li>Release engine hood through open window.</li> <li>Open engine hood.</li> <li>Deactivate ATA.</li> </ul>	Alarm horn sounds, lights flash.	23 ⇒ 8.0
⇒ 5.0 Activate ATA via trunk lid	<ul> <li>Open trunk lid.</li> <li>Lock driver's door with key. (up to M. Y. 1997)</li> <li>Lock passenger door with key. (as of M. Y. 1997)</li> <li>Turn off trunk lamp (rotary tumbler switch open).</li> <li>Wait approximately 15 seconds.</li> <li>Turn on trunk lamp. (rotary tumbler switch closed)</li> <li>Deactivate ATA.</li> </ul>	Alarm horn sounds, lights flash.	23 ⇒ 7.0

<sup>1)</sup> Observe Preparation for Test, see 22.

Test step/Test scope	Test condition	Nominal value	Possible cause/Remedy 1)
⇒ 6.0 Activate ATA via ignition	<ul> <li>Sit in driver's seat.</li> <li>Open driver's door window (up to M. Y. 1997).</li> <li>Open passenger door window (as of M. Y. 1997).</li> <li>Lock vehicle with key from driver's door by reaching through open window (up to M. Y. 1997).</li> <li>Lock vehicle with key from passenger door by reaching through open window (as of M. Y. 1997).</li> <li>Wait approximately 15 seconds.</li> <li>Turn ignition ON.</li> <li>Measure duration of alarm (approx. 30 sec).</li> <li>Deactivate ATA.</li> </ul>	Alarm horn sounds, lights flash.	23 ⇒ 11.0

<sup>1)</sup> Observe Preparation for Test, see 22.

Test step/Test scope	Test condition	Nominal value	Possible cause/Remedy 1)
⇒ 7.0 Activate ATA via service brake	<ul> <li>Sit in driver's seat.</li> <li>Open driver's door window (up to M. Y. 1997).</li> <li>Open passenger door window (as of M. Y. 1997).</li> <li>Lock vehicle with key from driver's door by reaching through open window (up to M. Y. 1997).</li> <li>Lock vehicle with key from passenger door by reaching through open window (as of M. Y. 1997).</li> <li>Wait approximately 15 seconds.</li> </ul>	Alarm harn agunda lighta flagh	23 ⇒ 9.0
	<ul> <li>Turn ignition ON.</li> <li>Measure duration of alarm (approx. 30 seconds).</li> <li>When cycle ends, with ignition ON, step on service brake.</li> <li>Deactivate ATA.</li> </ul>	Alarm horn sounds, lights flash.  Alarm horn sounds, lights flash.	

Observe Preparation for Test, see 22.

Test step/Test scope	Test condition	Nominal value	Possible cause/Remedy 1)
⇒ 8.0 Activate ATA via Radio (running change during M. Y. 1996)	<ul> <li>Sit in driver's seat.</li> <li>Open driver's door window (up to M. Y. 1997).</li> <li>Open passenger door window (as of M. Y. 1997).</li> <li>Lock vehicle with key from driver's door by reaching through open window (up to M. Y. 1997).</li> <li>Lock vehicle with key from passenger door by reaching through open window (as of M. Y. 1997).</li> <li>Wait approximately 15 seconds.</li> <li>Remove radio.</li> <li>Deactivate ATA.</li> <li>Note: After Function Test radio must be recoded.</li> </ul>	Alarm horn sounds, lights flash.	23 ⇒ 10.0 Radio contact separated.

Observe Preparation for Test, see 22.

Test step/Test scope		Test condition	Nominal value	Possible cause/Remedy 1)
⇒ 9.0	Not applicable for U.S.A. vehicles	_	_	_
⇒ 10.0	Not applicable for U.S.A. vehicles	_	_	_
⇒ 11.0	Not applicable for U.S.A. vehicles	_	_	_
<b>⇒</b> 12.0	ATA Status indicator (E33)	<ul><li>Lock vehicle.</li><li>Wait approximately 15 seconds.</li></ul>	LED in ATA status indicator (center console) blinks.	23 ⇒ 26.0
<b>⇒</b> 13.0	Starter lock-out 2)	<ul> <li>Sit in driver's seat.</li> <li>Open driver's door window (up to M. Y. 1997).</li> <li>Open passenger door window (as of M. Y. 1997).</li> <li>Lock vehicle with key from driver's door by reaching through open window (up to M. Y. 1997).</li> <li>Lock vehicle with key from passenger door by reaching through open window (as of M. Y. 1997).</li> <li>Wait approximately 15 seconds.</li> <li>Start engine.</li> <li>Deactivate ATA.</li> <li>Start engine.</li> </ul>	Alarm sounds, engine <b>will not</b> crank. Engine starts.	23 ⇒ 25.0

<sup>1)</sup> Observe Preparation for Test, see 22.

<sup>2)</sup> As of 01/94, starter lock-out function controlled by central locking system (PSE control module).

Test step/Test scope		Test condition	Nominal value	Possible cause/Remedy 1)
<b>⇒</b> 14.0	Not applicable for U.S.A. vehicles	_	_	_
<b>⇒</b> 15.0	Not applicable for U.S.A. vehicles	_	_	_

<sup>1)</sup> Observe Preparation for Test, see 22.