

## Hydraulic Test Program - Test


Test step D	Test scope		Test connection	Test condition	Nominal value	Possible cause/Remedy
⇒ 1.0	리 ASR charging 건식			Ignition: <b>ON</b> (for a maximum of 60 s)	1.8 – 11 bar <sup>2</sup> )	Wiring, Hydraulic connections leaking, M15
⇒ 2.0	旧 ABS/ASR hydr 21 pressure/retur 24 (A7/3m1) and preservoir	n pump			110 bar, then increase slowly to 150 – 200 bar. Charging time:	Hydraulic connections leaking. If there is no pressure increase, or the increase takes too long (more than 60 s): $23 \Rightarrow 22.0$ , A7/3. If the pressure increase quickly to < 50 bar, and then slowly increases to maximum value, or then increases quickly and steadily to maximum value: Replace pressure reservoir.

.

## Hydraulic Test Program - Test










ABS/ASR hydraulic unit (A7/3) vent screw "SP"

Figure 2

M15 ASR charging pump


Figure 3 Model 124 N30/1 ABS/ASR control module

## Hydraulic Test Program - Test



P42-2406-13

Figure 4 Model 140 N30/1 ABS/ASR control module



P42-5138-13






Figure 6

Connection of brake bleeder to brake fluid reservoir

.