9.5 ME - SFI (ME1.0) Engine 119

Diagnosis - Complaint Related Diagnostic Chart - Injection/Ignition

Complaint/Problem	Possible cause	Test step/Remedy 1)	Actual value Engine test Menu item
Engine starts and accelerates poorly when cold	Injector (Y62) activation and injection duration. Hot film MAF sensor (B2/5). ECT sensor (B11/4). Ignition voltage too low. Intake air leak.	$23 \Rightarrow 17.0 - 24.0$ $23 \Rightarrow 4.0 - 5.0$ $23 \Rightarrow 8.0$ $24 \Rightarrow 30.0$ Remedy leak.	2/7 1/7 3/7 -
Engine does not start	No voltage supply from base module (N16/1). Malfunction of drive authorization system (DAS) . Fuel pumps defective. No compression, oil pressure too high. Ignition voltage too low.	$23 \Rightarrow 1.0 - 3.0$ $23 \Rightarrow 37.0$ $34 \Rightarrow 2.0$ check compression and oil pressure. $24 \Rightarrow 30.0$	- DAS 1/1 - -
Engine has uneven idle	Camshaft timing. Injector (Y62) activation and injection duration. Intake air leak.	23 ⇒ 27.0 − 30.0 23 ⇒ 17.0 − 24.0 Remedy leak.	2/7 2/7 –
Engine has insufficient output	TWC flow restricted. Left or right O2S 1 (G3/3 or G3/4) (before TWC). ECT sensor (B11/4). Hot film MAF sensor (B2/5). Camshaft timing.	Check exhaust back pressure, see DM, Engines, Vol. 1, section A, "Engine Output" $23 \Rightarrow 11.0 - 12.0$ $23 \Rightarrow 8.0$ $23 \Rightarrow 4.0 - 5.0$ $23 \Rightarrow 27.0 - 30.0$	- 5/7 3/7 1/7 2/7

¹⁾ Observe Preparation for Test, see 22.

9.5 ME - SFI (ME1.0) Engine 119

Diagnosis - Complaint Related Diagnostic Chart - Injection/Ignition

Complaint/Problem	Possible cause	Test step/Remedy 1)	Actual value Engine test Menu item
Engine runs unevenly (shakes)	Injector (Y62) activation and injection duration. Injector leaking, poor spray pattern. Left or right O2S 1 (G3/3 or G3/4) (before TWC). Ignition voltage too low. Compression on one or more cylinders too low. Intake air leak.	$23 \Rightarrow 17.0 - 24.0$ $36 \Rightarrow 1.0$ $23 \Rightarrow 11.0 - 12.0$ $24 \Rightarrow 30.0$ Check compression. Remedy leak.	2/7 - 5/7 - -
Engine runs unevenly (misfiring)	Ignition voltage too low. Hot film MAF sensor (B2/5).	$24 \Rightarrow 30.0$ $23 \Rightarrow 4.0 - 5.0$	- 1/7
Engine surges after cold start	Intake air leak.	Remedy leak.	-
Transition failure during warm-up	ECT sensor (B11/4). Hot film MAF sensor (B2/5). Intake air leak.	$23 \Rightarrow 8.0$ $23 \Rightarrow 4.0 - 5.0$ Remedy leak.	3/7 1/7 -
Transition failure when warm or high fuel consumption	Left or right O2S 1 (G3/3 or G3/4) (before TWC). Purge control valve (Y58/1) stuck in open position.	23 ⇒ 11.0 − 12.0 23 ⇒ 31.0	5/7 3/7
Engine vibrates	Hot film MAF sensor (B2/5). Ignition voltage too low. Left or right O2S 1 (G3/3 or G3/4) (before TWC).	$23 \Rightarrow 4.0 - 5.0$ $24 \Rightarrow 30.0$ $23 \Rightarrow 11.0 - 12.0$	1/7 - 5/7
EPC MIL (A1e43) illuminates and EA is in "limphome" mode	Nominal value potentiometer in pedal value sensor (B37). EA/CC/ISC actuator actual value potentiometer.	$25 \Rightarrow 4.0 - 5.0$ $25 \Rightarrow 6.0 - 7.0$	4/7 4/7

¹⁾ Observe Preparation for Test, see 22.

12/2