9.6 ME-SFI Engine 120

### **Diagnosis – Complaint Related Diagnostic Chart – Injection/Ignition**

# **⚠** WARNING!

Risk of severe injury when touching ignition parts which produce high voltages. Do not touch ignition components.

Persons with heart pacemakers are not to perform repairs on this type of ignition system.

#### **Preparation for Test:**

1. Review 11, 21, 22, 23, 24, 31, 33

Complaint/Problem	Possible cause	Test step/Remedy 1)	Actual value Engine test Menu item
Engine starts and accelerates poorly when cold	Injector (Y62) control and injection duration. Hot film MAF sensor (B2/6 or B2/7). ECT sensor (B11/9 or B11/10). Ignition voltage too low. Intake air leak.	$23 \Rightarrow 14.0 - 19.0$ $23 \Rightarrow 4.0$ $23 \Rightarrow 7.0$ $24 \Rightarrow 24.0$ Remedy leak.	2/7 1/7 3/7 - -
Engine does not start	No voltage supply from base module (N16/1).  Malfunction of drive authorization system (DAS).  Fuel pumps defective.  No compression, oil pressure too high.  Ignition voltage too low.	$23 \Rightarrow 1.0 - 3.0$ $23 \Rightarrow 30.0$ $34 \Rightarrow 2.0$ Check compression and oil pressure. $24 \Rightarrow 24.0$	- DAS 1/1 - -
Engine has uneven idle	Camshaft timing. Injector (Y62) control and injection duration. Intake air leak.	23 ⇒ 22.0 – 23.0 23 ⇒ 14.0 – 19.0 Remedy leak.	2/7 2/7 -

<sup>1)</sup> Observe Preparation for Test, see 22.

Diagnostic Manual • Engines • 10/01 9.6 ME-SFI 12/1

9.6 ME-SFI Engine 120

## Diagnosis – Complaint Related Diagnostic Chart – Injection/Ignition

Complaint/Problem	Possible cause	Test step/Remedy 1)	Actual value Engine test Menu item
Engine has insufficient output	TWC flow restricted.  Left or right O2S 1 (G3/3 or G3/4) (before TWC).  ECT sensor (B11/9 or B11/10).  Hot film MAF sensor (B2/6 or B2/7).  Camshaft timing.	Check exhaust back pressure, see DM, Engines, Vol. 1, section A, "Engine Output" $23 \Rightarrow 10.0 - 11.0$ $23 \Rightarrow 7.0$ $23 \Rightarrow 4.0$ $23 \Rightarrow 22.0 - 23.0$	- 5/7 3/7 1/7 2/7
Engine runs unevenly (shakes)	Injector (Y62) control and injection duration. Injector leaking, spray pattern. Left or right O2S 1 (G3/3 or G3/4) (before TWC). Ignition voltage too low. Compression on one or more cylinders too low. Intake air leak.	$23 \Rightarrow 14.0 - 19.0$ $36 \Rightarrow 1.0$ $23 \Rightarrow 10.0 - 11.0$ $24 \Rightarrow 24.0$ Check compression. Remedy leak.	2/7 - 5/7 - -
Engine runs unevenly (misfiring)	Ignition voltage too low. Hot film MAF sensor (B2/6 or B2/7).	$24 \Rightarrow 24.0$ $23 \Rightarrow 4.0$	_ 1/7
Engine surges after cold start	Intake air leak.	Remedy leak.	_
Transition failure during warm-up	ECT sensor (B11/9 or B11/10). Hot film MAF sensor (B2/6 or B2/7). Intake air leak.	23 ⇒ 7.0 23 ⇒ 4.0 Remedy leak.	3/7 1/7 -
Transition failure when warm or with increased fuel consumption	Left or right O2S 1 (G3/3 or G3/4) (before TWC). Purge control valve (Y58/2 or Y58/3) stuck in open position.	$23 \Rightarrow 10.0 - 11.0$ $23 \Rightarrow 24.0 - 25.0$	3/7

<sup>1)</sup> Observe Preparation for Test, see 22.

Diagnostic Manual • Engines • 10/01 9.6 ME-SFI 12/2

9.6 ME-SFI Engine 120

## Diagnosis – Complaint Related Diagnostic Chart – Injection/Ignition

Complaint/Problem	Possible cause	Test step/Remedy 1)	Actual value Engine test Menu item
Engine vibrates	Hot film MAF sensor (B2/6 or B2/7). Ignition voltage too low. Left or right O2S 1 (G3/3 or G3/4) (before TWC).	$23 \Rightarrow 4.0$ $24 \Rightarrow 24.0$ $23 \Rightarrow 10.0 - 11.0$	1/7 - 5/7
EPC MIL (A1e43) illuminates and EA is in "limphome" mode	Nominal value potentiometer in pedal value sensor (B37).  EA/CC/ISC actuator actual value potentiometer.	$25 \Rightarrow 4.0 - 5.0$ $25 \Rightarrow 6.0 - 7.0$	4/7 4/7

Observe Preparation for Test, see 22.

Diagnostic Manual • Engines • 10/01 9.6 ME-SFI 12/3