

5.5 Model 140 (with Bose® Sound System), as of M.Y. 1994

	Page
Technical Changes	10/1
Diagnosis	
Function Test	11/1
Complaint Related Diagnostic Chart	12/1
Electrical Test Program	
Component Locations	21/1
Preparation for Test	22/1
Test	23/1

Technical Changes

Manufacturer Code	Model	LHS ¹⁾ RHS ¹⁾	Manuf. plant	As of chassis number	Up to chassis number	As of production date	Up to production date	Type and reason for change	Reference/Remarks
WDB	140					approx. 07/95		Revised nominal values.	

- 1) LHS: Lefthand steering
 RHS: Righthand steering

Diagnosis – Function Test

Function Test Explanation

For the Function Test, adjust the radio as follows:

- Tune-in a strong radio station (music), or play a cassette or CD.
- Set fader, bass, treble and balance to center range (RESET reading in display window).
- Listen to each individual loudspeaker at the various locations.

5.5 Loudspeaker Systems (LS)

Model 140, as of M.Y. 1994

Diagnosis – Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy ¹⁾
Loudspeaker system not functioning	Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 1.0
Left front door speaker group (H4/1) not functioning	H4/1 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 2.0
Right front door speaker group (H4/2) not functioning	H4/2 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 3.0
Sedan Left rear door speaker (H4/3) not functioning Coupé Left front door speaker (H4/5) not functioning	H4/3 or H4/5 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 4.0
Sedan Right rear door speaker (H4/4) not functioning Coupé Right front door speaker (H4/6) not functioning	H4/4 or H4/6 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 5.0
Left rear speaker group (H4/7) not functioning	H4/7 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 6.0
Right rear speaker group (H4/8) not functioning	H4/8 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 7.0
Center fill tweeter speaker (H4/11), in mirror base, not functioning	H4/11 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 8.0

¹⁾ Observe Preparation for Test, see 22.

Electrical Test Program – Component Locations

Loudspeaker Components in Front Passenger Compartment (Sedan)




Figure 1

- A2 Radio
- H4/1 Left front door speaker group
- H4/2 Right front door speaker group (not shown)
- H4/11 Center fill tweeter speaker

P82-7026-57

Electrical Test Program – Component Locations

Loudspeaker Components in Rear Passenger Compartment (Sedan)




Figure 2

- H4/3 Left rear door speaker
- H4/4 Right rear door speaker (not shown)
- H4/7 Left rear speaker group
- H4/8 Left rear speaker group (not shown)
- N40/3 Left/right audio power amplifier

P82-7030-57

Electrical Test Program – Preparation for Test

1. Battery voltage 11–14 V.
2. Check fuses.
3. Radio OK.
4. Loudspeaker for sound system installed (Marking: blue label).
5. Connections to N40/3 OK.


Electrical wiring diagrams:

Electrical Troubleshooting Manual, Model 140

Note:

To prevent damage to the radio and left/right audio power amplifier, the connectors must only be removed or installed with the ignition and radio **OFF**.

Special Tools





















201 589 00 99 00
Electrical connecting set

Conventional tools, test equipment

Description	Brand, model, etc.
Digital multimeter ¹⁾	Fluke models 23, 83, 85, 87

¹⁾ Available through the MBUSA Standard Equipment Program.










Electrical Test Program – Test

⇒	Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
1.0	Left/right audio power amplifier (N40/3) Voltage supply	9 —   26 — 	Radio (A2): OFF Disconnect N40/3.	11 – 14 V	Fuse F4-16, Fuse in N40/3 (Figure 1), Ground (W6), Wiring, ⇒ 1.1, If nominal value is OK: Replace N40/3.
1.1	Control voltage from radio (A2)	9 —   8 — 	Disconnect N40/3. Radio (A2): ON	11 – 14 V	Wiring, Radio (see section 3.1 23), ⇒ 1.2.
1.2	Speaker signal from radio (A2)	N40/3 left front: 10 —   18 —  right front: 1 —   2 —  left rear: 3 —   5 —  right rear: 4 —   6 — 	Disconnect N40/3. Turn volume control to maximum. Radio (A2): ON	> 0.2 V A momentary lower value is permissible.	Wiring, Radio (see section 3.1 23).

5.5 Loudspeaker Systems (LS)

Model 140, as of M.Y. 1994

Electrical Test Program – Test

⇒	Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
2.0	Left front door speaker group (H4/1)	H4/1 21 —  — 13 9 —  — 13 21 —  — 9	Radio (A2): OFF Disconnect N40/3.	Up to 06/95: 0.6 – 1.2 Ω As of 07/95: 1.5 – 2.5 Ω ∞ Ω ∞ Ω	Wiring, H4/1, If nominal values are OK: Replace N40/3.
3.0	Right front door speaker group (H4/2)	H4/2 14 —  — 22 9 —  — 22 14 —  — 9	Radio (A2): OFF Disconnect N40/3.	Up to 06/95: 0.6 – 1.2 Ω As of 07/95: 1.5 – 2.5 Ω ∞ Ω ∞ Ω	Wiring, H4/2, If nominal values are OK: Replace N40/3.
4.0	Sedan Left rear door speaker (H4/3) Coupé Left front door speaker (H4/5)	H4/3 or H4/5 15 —  — 23 9 —  — 23 15 —  — 9	Radio (A2): OFF Disconnect N40/3.	Up to 06/95: 3.2 – 4.0 Ω As of 07/95: 1.5 – 2.5 Ω ∞ Ω ∞ Ω	Wiring, H4/3 or H4/5, If nominal values are OK: Replace N40/3.


Electrical Test Program – Test

⇒	Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
5.0	Sedan Right rear door speaker (H4/4) Coupé Right front door speaker (H4/6)	H4/4 or H4/6 17 —(—(—(Ω+ —) 25 9 —(—(—(Ω+ —) 25 17 —(—(—(Ω+ —) 9	Radio (A2): OFF Disconnect N40/3.	Up to 06/95: 3.2 – 4.0 Ω As of 07/95: 1.5 – 2.5 Ω ∞ Ω ∞ Ω	Wiring, H4/4 or H4/6, If nominal values are OK: Replace N40/3.
6.0	Left rear door speaker group (H4/7)	H4/7 12 —(—(—(Ω+ —) 20 9 —(—(—(Ω+ —) 20 12 —(—(—(Ω+ —) 9	Radio (A2): OFF Disconnect N40/3.	0.6 – 1.4 Ω ∞ Ω ∞ Ω	Wiring, ⇒ 6.1, If nominal values are OK: Replace N40/3.
6.1	Left rear door speaker group (H4/7) Individual speakers (H4/7h1 or H4/7h2)	H4/7h1 or H4/7h2 —(—(—(Ω+ —) —)	Radio (A2): OFF Disconnect speaker group connectors.	1.8 – 2.4 Ω	H4/7h1 or H4/7h2.
7.0	Right rear door speaker group (H4/8)	H4/8 11 —(—(—(Ω+ —) 19 9 —(—(—(Ω+ —) 19 11 —(—(—(Ω+ —) 9	Radio (A2): OFF Disconnect N40/3.	0.6 – 1.4 Ω ∞ Ω ∞ Ω	Wiring, ⇒ 7.1, If nominal values are OK: Replace N40/3.

Electrical Test Program – Test

⇒	Test scope	Test connection	Test condition	Nominal value	Possible cause/Remedy
7.1	Right rear door speaker group (H4/8) Individual speakers (H4/8h1 or H4/8h2)	H4/8h1 or H4/8h2 	Radio (A2): OFF Disconnect speaker group connectors.	1.8 – 2.4 Ω	H4/8h1 or H4/8h2.
8.0	Center fill tweeter speaker (H4/11)	H4/11 	Radio (A2): OFF Disconnect N40/3.	3.6 – 4.2 Ω ∞ Ω ∞ Ω	Wiring, H4/11, If nominal values are OK: Replace N40/3.

Electrical Test Program – Test



P82-7024-13

Figure 1

- N40/3 Left/right audio power amplifier
- a Fuse