

Diagnosis – Technical Changes

Prod. code	Model	LL ¹⁾ RL ¹⁾	Manuf. plant	As of chassis number	Up to chassis number	As of production date	Up to production date	Type and reason for change	Reference/Remarks
WDB	140					12/93		Activation of starter relay module (K38): Vehicles with RCL via PSE control module.	
WDB	140							Radio contact deleted with later radio versions. (running change during M.Y. 1996)	

1) LL: Left hand drive
RL: Right hand drive