

Diagnosis – Technical Changes


Version start dates/Changes/Innovations (Model 202)

World wide Manuf. code	Model	LHS ¹⁾ RHS ¹⁾	Manuf. plant	As of chassis number	Up to chassis number	As of production date	Up to production date	Type and reason for change	Reference/Remarks
WDB	202						12/93	Starter lock-out relay (K38) located on interior A-pillar bottom, activation is via ATA.	
WDB	202					01/94		Starter lock-out relay (K38) located on left side of dashboard crossmember. Activation on vehicles w/o IRCL via PSE. On vehicles with IRCL via IRCL control module.	
WDB	202					01/94		On vehicles with IRCL (code 800) the locknut switch is not installed, except (USA)	
WDB	202					03/94		Deactivation of the interior motion sensor no longer via button on left infrared transmitter and receiver (interior motion system) (A26/4), but instead together with the anti-tow protection system via switch on the center console.	
WDB	202							Radio contact deleted with introduction of new radio generation.	

1) LHS: Left hand steering
RHS: Right hand steering

Diagnosis – Technical Changes

Version start dates/Changes/Innovations (Model 202 continued)

World wide Manuf. code	Model	LHS ¹⁾ RHS ¹⁾	Manuf. plant	As of chassis number	Up to chassis number	As of production date	Up to production date	Type and reason for change	Reference/Remarks
WDB	202					09/96		New interior protection system, the IR interior motion ATA control module (N26/3) was deleted as a result.	
WDB	202					06/97		ATA was combined into the PSE control module (A37).	
WDB	202					06/98		Alarm siren with auxiliary battery (H3/1) replaces the Alarm horn (H3). Optional ATA includes anti-tow protection system.	
WDB	202					06/98		New infrared interior motion sensor (One sensor replaces previously used two sensors)	 For sedan only.

1) LHS: Left hand steering
RHS: Right hand steering

Diagnosis – Technical Changes

Version start dates/Changes/Innovations (Model 208)

World wide Manuf. code	Model	LHS ¹⁾ RHS ¹⁾	Manuf. plant	As of chassis number	Up to chassis number	As of production date	Up to production date	Type and reason for change	Reference/Remarks
WDB	208							No interior motion sensor for 208 Cabrio.	
WDB	208					06/98		Alarm siren with auxiliary battery (H3/1) replaces the alarm horn (H3). Optional ATA includes anti-tow protection system.	

1) LHS: Left hand steering
RHS: Right hand steering

Diagnosis – Technical Changes

Version start dates/Changes/Innovations (Model 210)

World wide Manuf. code	Model	LHS ¹⁾ RHS ¹⁾	Manuf. plant	As of chassis number	Up to chassis number	As of production date	Up to production date	Type and reason for change	Reference/Remarks
WDB	210					03/97		ATA has been combined into the PSE control module (A37) (complete network), DAS 3	With 4-MATIC as of production start-up.
WDB	210					06/98		Alarm siren with auxiliary battery (H3/1) replaces the Alarm horn (H3). Optional ATA includes anti-tow protection system.	
WDB	210					06/98		New infrared interior motion sensor (One sensor replaces previously used two sensors)	i For sedan only.
WDB	210					06/99		New infrared interior motion sensor (One sensor replaces previously used two sensors)	i For wagen only.

1) LHS: Left hand steering
RHS: Right hand steering