Diagnosis – Function Test

Life threatening injures possible if following protective measures are not followed.

Risk of severe injury, due to uneven placement of lift arms/lift arm supports, as well as the support and lifting of vehicle components, there is the possibility of the vehicle slipping while on the lift.

Danger of vehicle toppling off of lift due to irregular weight distribution after the removal of components and axles.

Protective measures:

- Center vehicle (fore, aft and across) properly on both sides of the lift columns.
- When supporting components while the vehicle is on a lift, ensure that the vehicle is not lifted from the lift arms, therefore secure vehicle to the lift arms as well.
- Ensure that the lift arm supports are even and parallel to each other when lifting the vehicle.

Protective measures continued:

- Prior to lift vehicle completely (wheels still in contact with floor), ensure that the lift arm supports are correctly placed unto the vehicle contact points.
- Prior to removing the axles or components from the vehicle while on the lift, secure the vehicle to the lift arms or place sand bags inside the vehicle to ensure proper weight distribution to prevent toppling of the vehicle from the lift.
- Basically obey all the rules/guide lines regarding the lifting of vehicles as stated in the operator's manual by the lift manufacturer.

Control Module Adaption:

After the swap of the ESP/SPS/BAS or ESP/BAS control module (N47-5), it is important to perform the adaption procedure, since the control module must learn the values for the BAS solenoid valves. See HHT menu.

Preparation for Test:

Review 11, 13, 20, 21, 23

Diagnosis – Function Test – ABS Lateral Acceleration Sensor (B43)

	Procedure	Hints
	i This function test applies as of M.Y. 2000 only The following description of the driving test is to be performed only upon the replacement or swap of the ABS Lateral Acceleration sensor (B43) and/or the Rotating Speed Sensor for ESP (B45).	 Via this driving test, the following faults can be isolated: improperly connected connectors of the sensors., twisted wires of the respective sensors sensors with implausible signals
1	Activate Test: Release driving test via Star Diagnosis	iEngine is running (idle).The release of the driving test remains active even after the ignitionis switched OFF or ON. The driving test is ended when the drivingtest procedure is completed or it is deactivaded via Star Diagnosis.BAS/ESP MIL (A1e47) and ABS MIL (A1e17) are illuminated:Indicating to the driver: ABS: ONESP: OFFThus after the release, the ESP system is OFF, however the functionsof the BAS, ABS, and ASR systems remain active.iWithin the DTC fault memory the following is entered: "Driving TestActive". This DTC will be erased automatically upon completion ofthe Driving Test.

Diagnosis – Function Test – ABS Lateral Acceleration Sensor (B43) (continued)

Procedure	Hints
i The following description of the driving test is to be performed only upon the replacement or swap of the ABS Lateral Acceleration sensor (B43) and/or the Rotating Speed Sensor for ESP (B45) .	 Via this driving test, the following faults can be isolated: improperly connected connectors of the sensors., twisted wires of the respective sensors sensors with implausible signals
2 Stationary deviation of the ABS Lateral Acceleration Sensor (B43) and/or Rotating Speed Sensor of ESP (B45): Press ESP switch in direction: ON Vehicle is stationary and the steering wheel is pointed straight ahead.	i By pressing the ESP switch, a time window of 20 seconds is started, which can lengthened in time span as desired. BAS/ESP MIL (A1e47) begins to blink as an indication that the stationary deviation test of the ABS Lateral Acceleration Sensor has started. Upon correct procedure the BAS/ESP MIL (A1e47) will illuminate. This then is the signal to perform the driving test as described in point 3 of the menu. Should the vehicle be moved in any way during the stationary deviation test, the stationary deviation test of the ABS Lateral Acceleration Sensor will not be performed. The BAS/ESP MIL (A1e47) will be illuminated.

Diagnosis – Function Test – ABS Lateral Acceleration Sensor (B43) (continued)

	Procedure	Hints
3	Dynamic testing of the ABS Lateral Acceleration Sensor (B43) and/or Rotating Speed Sensor of ESP (B45): Drive the vehicle in a forward direction at a speed between 5 to 25 km/h (3 to 15 mph). After approx. 20 feet, driving at a constant speed, turn the steering wheel either left or right, but not more then 360°.	i The ESP/BAS control module (N47-5) performs an evaluation of the rotating signals and lateral accleration signals. After a successful completion, the BAS/ESP MIL (A1e47) and ABS MIL (A1e17) will go out.
		In case of fault: ABS MIL (A1e17) is illuminated: Driving test not successful. Repeat the dynamic driving test (menu item 3). BAS/ESP MIL (A1e47) is illuminated: Driving test not successful. Readout DTC memory.

Diagnosis – Function Test – Rotating Speed Sensor for ESP (B45)

	Procedure	Hints
	i This function test applies as of M. Y. 2000 only The following description of the driving test is to be performed only upon the replacement or swap of the ABS Lateral Acceleration sensor (B43) and/or the Rotating Speed Sensor for ESP (B45).	 Via this driving test, the following faults can be isolated: improperly connected connectors of the sensors., twisted wires of the respective sensors sensors with implausible signals
1	Activate Test: Release driving test via Star Diagnosis	 I Engine is running (idle). The release of the driving test remains active even after the ignition is switched OFF or ON. The driving test is ended when the driving test procedure is completed or it is deactivaded via Star Diagnosis. BAS/ESP MIL (A1e47) and ABS MIL (A1e17) are illuminated: Indicating to the driver: ABS: ON ESP: OFF Thus after the release, the ESP system is OFF, however the functions of the BAS, ABS, and ASR systems remain active. I Within the DTC fault memory the following is entered: "Driving Test Active". This DTC will be erased automatically upon completion of the Driving Test.

Diagnosis – Function Test – Rotating Speed Sensor for ESP (B45) (continued)

	Procedure	Hints
	i The following description of the driving test is to be performed only upon the replacement or swap of the ABS Lateral Acceleration sensor (B43) and/or the Rotating Speed Sensor for ESP (B45).	 Via this driving test, the following faults can be isolated: improperly connected connectors of the sensors., twisted wires of the respective sensors sensors with implausible signals
2	Stationary deviation of the ABS Lateral Acceleration Sensor (B43) and/or Rotating Speed Sensor of ESP (B45): Press ESP switch in direction: ON Vehicle is stationary and the steering wheel is pointed straight ahead.	İ By pressing the ESP switch, a time window of 20 seconds is started, which can lengthed in time span as desired. BAS/ESP MIL (A1e47) begins to blink as an indication that the stationary deviation test of the ABS Lateral Acceleration Sensor has started. Upon correct procedure the BAS/ESP MIL (A1e47) will illuminate. This then is the signal to perform the driving test as described in point 3 of the menu. Should the vehicle be moved in any way during the stationary deviation test, the stationary deviation test of the ABS Lateral Acceleration Sensor will not be performed. The BAS/ESP MIL (A1e47) will be illuminated.
		In case of fault: Read out the DTC fault code memory.

Diagnosis – Function Test – Rotating Speed Sensor for ESP (B45) (continued)

	Procedure	Hints
3	Dynamic testing of the ABS Lateral Acceleration Sensor (B43) and/or Rotating Speed Sensor of ESP (B45): Drive the vehicle in a forward direction at a speed between 5 to 25 km/h (3 to 15 mph). After approx. 20 feet, driving at a constant speed, turn the steering wheel either left or right, but not more then 360°.	i The ESP/BAS control module (N47-5) performs an evaluation of the rotating signals and lateral accleration signals. After a successful completion, the BAS/ESP MIL (A1e47) and ABS MIL (A1e17) will go out.
		In case of fault: ABS MIL (A1e17) is illuminated: Driving test not successful. Repeat the dynamic driving test (menu item 3). BAS/ESP MIL (A1e47) is illuminated: Driving test not successful. Readout DTC memory.