

Diagnosis – Function Test

Test step/Test scope	Test condition	Nominal value	Possible cause/Remedy ¹⁾
⇒ 1.0 Function test	Low beam switched on.	After 1 – 2 seconds 50% of maximum illumination. After 30 seconds maximum illumination attained.	23 Test

¹⁾ Observe Preparation for Test, see 22.

 **DANGER!**

High voltage components with switched on Xenon headlamps.

Therefore, when Xenon headlamps are switched on, do not touch any of the high voltage components.