



## Diagnosis – Technical Changes

### Version start dates/Changes/Innovations

World wide Manuf. code	Model	LHS <sup>1)</sup> RHS <sup>1)</sup>	Manuf. plant	As of chassis number	Up to chassis number	As of production date	Up to production date	Type and reason for change	Reference/Remarks
WDB	129					01/94		Vehicles using IRCL (code 880) can not be activated or deactivated via mechanical key.	
WDB	129					06/97		Introduction of DAS2	
WDB	129					06/97		Activation and deactivated of ATA via mechanical key and lock nut switch.	(only  )
WDB	129					06/97		 version deleted.	
WDB	129					06/98		Alarm siren (H3) is being replaced with alarm siren with auxiliary battery (H3/1) in model production. Anti-tow sensor included with optional version of ATA.	

1) LHS: Left hand steering  
RHS: Right hand steering