

### Diagnosis – Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy <sup>1)</sup>
Complete left and right outside rearview mirror adjustment does not function	Center console switch group (S21), Voltage supply Outside rearview mirror-left/right switch (S21s8)	23 ⇒ 1.0 23 ⇒ 2.0
Left outside rearview mirror Vertical adjustment does not function	Outside rearview mirror-vertical adjustment switch (S21s6) Mirror adjustment motor (up/down) (M21/1m1)	23 ⇒ 3.0 23 ⇒ 5.0
Left outside rearview mirror Horizontal adjustment does not function	Outside rearview mirror-horizontal adjustment switch (S21s7) Mirror adjustment motor (in/out) (M21/1m2)	23 ⇒ 4.0 23 ⇒ 6.0
Right outside rearview mirror Vertical adjustment does not function	Outside rearview mirror-vertical adjustment switch (S21s6) Mirror adjustment motor (up/down) (M21/2m1)	23 ⇒ 7.0 23 ⇒ 9.0
Right outside rearview mirror Horizontal adjustment does not function	Outside rearview mirror-horizontal adjustment switch (S21s7) Mirror adjustment motor (in/out) (M21/2m2)	23 ⇒ 8.0 23 ⇒ 10.0
Mirror heating for left outside rearview mirror does not function	Mirror heater (M21/1r1)	23 ⇒ 11.0
Mirror heating for right outside rearview mirror does not function	Mirror heater (M21/2r1)	23 ⇒ 12.0

<sup>1)</sup> Observe Preparation for Test, see 22.