


Diagnostics Troubleshooting chart



P91-0051-13A

Figure 1

- 1 Seat belt latch
- 2 Seat belt

Complaint	Possible cause	Test step ¹⁾ /remedy
After an accident both seat belt tensioners deployed and/or did not deploy.		23 ⇒ 1.0
Seat belt cannot be pulled out.		11 ⇒ 1.0
Seat belt latch does not work.		11 ⇒ 2.0 19.1 23 ⇒ 4.0 and/or 5.0
After connecting the seat belt latch the seat belt cannot be pulled out (no freeplay in seat belt).		11 ⇒ 2.0 19.1 23 ⇒ 4.0 and/or 5.0 19.1 23 ⇒ 9.0 and/or 10.0

¹⁾ Observe Preparation for Test, see 22.