

#### Diagnosis - Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Remedy/Test step
ASD MIL (A1e24) blinks when first using vehicle with new control module installed (N30/2).	Initialization of front rotors to rear axle has not been performed.	Drive vehicle up to a speed > 19 mph (30km/h) without applying the brakes. Once speed is attained, vehicle may be braked.