

Diagnosis - Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy ¹⁾
Electronic accelerator in "limp-home" mode	Closed throttle position switch (S29/3)	23 ⇒ 11.0
Engine speed limiter active at 1200 rpm (engine 104) or 1100 rpm (engine 119)	Fuel safety shut-off to LH-SFI control module (N3/1)	23 ⇒ 18.0

¹⁾ Observe Preparation for Test, see 22.