Diagnosis – Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy 1)
Cruise control/idle speed control in "limp-home" mode	CC/ISC control module (N4/3) voltage supply CC/ISC actuator (M16/2)	$23 \Rightarrow 1.0$ $23 \Rightarrow 3.0 - 10.0$
Engine speed limiter operates at 1200 – 1900 rpm	Fuel safety shut-off to engine control module (N3/4)	23 ⇒ 17.0

¹⁾ Observe Preparation for Test, see 22.