

5.5 Loudspeaker Systems (LS)

Model 140, as of M.Y. 1994

Diagnosis – Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy ¹⁾
Loudspeaker system not functioning	Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 1.0
Left front door speaker group (H4/1) not functioning	H4/1 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 2.0
Right front door speaker group (H4/2) not functioning	H4/2 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 3.0
Sedan Left rear door speaker (H4/3) not functioning Coupé Left front door speaker (H4/5) not functioning	H4/3 or H4/5 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 4.0
Sedan Right rear door speaker (H4/4) not functioning Coupé Right front door speaker (H4/6) not functioning	H4/4 or H4/6 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 5.0
Left rear speaker group (H4/7) not functioning	H4/7 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 6.0
Right rear speaker group (H4/8) not functioning	H4/8 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 7.0
Center fill tweeter speaker (H4/11), in mirror base, not functioning	H4/11 Left/right audio power amplifier (N40/3) Radio (A2)	23 ⇒ 8.0

¹⁾ Observe Preparation for Test, see 22.