

Diagnosis – Complaint Related Diagnostic Chart

Model 124, 163, 202, 208, 210
 Model 129 as of 06/98

Complaint/Problem	Possible cause	Notes	Test step/Remedy ¹⁾
CD changer not functioning at all	Voltage supply to CD changer (A2/6)	Model 124 and 202, 208, 210 up to 05/98 Model 163 Model 202, 208, 210 as of 06/98	23 ⇒ 1.0 23 ⇒ 2.0 23 ⇒ 3.0
CD changer will not load or unload CD's	Single CD adapter inserted Protective cover from CD not removed Voltage supply	Model 124 and 202, 208, 210 up to 05/98 Model 163 Model 202, 208, 210 as of 06/98	23 ⇒ 1.0 CD magazine, 23 ⇒ 2.0 23 ⇒ 3.0
CD changer command functions not working	CD changer (A2/6) Radio (A2)		23 ⇒ 4.0

¹⁾ Observe Preparation for Test, see 22.

Diagnosis – Complaint Related Diagnostic Chart

Model 129, 202, 208, 210 as of 06/98 with D2B fiber optics

Complaint/Problem/DTC	Possible cause	Notes	Test step/Remedy ¹⁾
P1240 P1250	CD changer (A2/6): Temperature too high		Lower vehicle's interior temperature
P1241 P1251	CD changer (A2/6): CD reading error		Check CD changer
P1242 P1252	CD changer (A2/6): CD magazine error		Check CD magazine
P1243 P1253	CD changer (A2/6): Hardware damage (mechanical)		Check hardware components - replace if necessary
P1244 P1254	CD changer (A2/6): Temperature too low		Warm up interior temperature

¹⁾ Observe Preparation for Test, see 22.