

Version Coding

Version coding must be undertaken when a new PSE control module (A37) is being replaced. Only after the coding procedure, the ATA functions of the PSE control module (A37) activated. Coding is menu driven via HHT.

Coding:

Entry into the version coding is via:

Body & accessories - ATA - Version coding



Correct version coding is a requirement for the proper indication of the Actual and Activation Menues as well as Fault Codes in the HHT.

Version coding

Version	Selection	Remarks
Country Version ATA	(USA) Headlamp illumination time (CH) up to 05/97 Rest of the world (B) (self activation)	
Anti-tow function	Yes No	
Alarm siren (up to 05/98 only: (B) (GB) (NL))	Yes No	Via a further sub-menu, the country version of the alarm siren is set.
Interior motion protection	Ultrasonic (as of 06/98) Ultrasonic (Model 208 cabriolet) Infrared NO	 Ultrasonic for Model 208 cabriolet is currently not available.