Diagnosis – Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy 1)
Engine does not run	DI control module (N1/3) voltage supply CKP sensor (L5) DI control module (N1/3)	$23 \Rightarrow 1.0 \text{ and } 2.0$ $23 \Rightarrow 4.0$

¹⁾ Observe Preparation for Test, see 22.