

## Diagnosis - Complaint Related Diagnostic Chart

## Electronic Accelerator

Complaint/Problem	Possible Cause	Remedy/Test Step <sup>1)</sup>
Electronic accelerator operates in "limp-home" mode	Closed throttle position switch (S29/3)	23 ⇒ 16.0
Engine speed limiter active at 1200 rpm	Fuel safety shut-off to LH-SFI control module (N3/3 or N3/2)	23 ⇒ 23.0, 24.0

<sup>1)</sup> Observe Preparation for Test, see 22.