

Diagnosis - Complaint Related Diagnostic Chart

Complaint/Problem	Possible cause	Test step/Remedy ¹⁾
Cruise control/idle speed control operates in "limp-home" mode	CC/ISC control module (N4/3) voltage supply CC/ISC actuator (M16/2)	23⇒ 1.0 23⇒ 3.0 – 10.0
Engine speed limiter active at 1200 – 1900 rpm	Fuel safety shut-off to LH-SFI control module (N3/1)	23 ⇒ 19.0

¹⁾ Observe Preparation for Test, see 22.