


Electrical Test Program – Component Locations



P82.62-0234-37

Figure 1

- A2/18 FM/AM rear window antenna amplifier
- a High frequency connection wire to radio
- b Automatic antenna control wire from radio
- c Signal wire from rear window antenna

Electrical Test Program – Component Locations




Figure 2

C3 Electrolytic capacitor (rear glass noise suppressor)
(right C-pillar)

P82.62-0235-37