

Diagnosis – Complaint Related Diagnostic Chart model 208

| Complaint/Problem | Possible cause | Test step/Remedy ¹⁾ |
|--|---------------------|--------------------------------|
| Left front door speaker (H4/31) not functioning | H4/31 Radio (A2) | 23 ⇒ 1.0 |
| Left front door mirror triangle speaker (H4/23) not functioning | H4/23 Radio (A2) | 23 ⇒ 2.0 |
| Left door speaker (H4/5) not functioning | H4/5 Radio (A2) | 23 ⇒ 3.0 |
| Left rear speaker (H4/7) not functioning | H4/7 Radio (A2) | 23 ⇒ 4.0 |
| Right front door speaker (H4/30) not functioning | H4/30 Radio (A2) | 23 ⇒ 5.0 |
| Right front door mirror triangle speaker (H4/24) not functioning | H4/24 Radio (A2) | 24 ⇒ 6.0 |
| Right door speaker (H4/6) not functioning | H4/6 Radio (A2) | 23 ⇒ 7.0 |
| Right rear speaker (H4/8) not functioning | H4/8 Radio (A2) | 23 ⇒ 8.0 |
| Dual cone speaker (H4/28) not functioning | H4/28 Radio (A2) | 23 ⇒ 9.0 |

¹⁾ Observe Preparation for Test, see 22.

Diagnosis – Complaint Related Diagnostic Chart model 163 (with Hi-Line Radio)

| Complaint/Problem | Possible cause | Test step/Remedy ¹⁾ |
|---|--------------------|--------------------------------|
| Left front door speaker (H4/5) not functioning | H4/5 Radio (A2) | 24 ⇒ 1.0 |
| Left rear door speaker (H4/3) not functioning | H4/3 Radio (A2) | 24 ⇒ 2.0 |
| Right front door speaker (H4/6) not functioning | H4/6 Radio (A2) | 24 ⇒ 3.0 |
| Right rear door speaker (H4/4) not functioning | H4/4 Radio (A2) | 24 ⇒ 4.0 |

¹⁾ Observe Preparation for Test, see 22.