

Electrical Test Program – Component Locations

Loudspeaker Components in Front Passenger Compartment (Sedan)




Figure 1

- A2 Radio
- H4/1 Left front door speaker group
- H4/2 Right front door speaker group (not shown)
- H4/11 Center fill tweeter speaker

P82-7026-57

Electrical Test Program – Component Locations

Loudspeaker Components in Rear Passenger Compartment (Sedan)




Figure 2

- H4/3 Left rear door speaker
- H4/4 Right rear door speaker (not shown)
- H4/7 Left rear speaker group
- H4/8 Left rear speaker group (not shown)
- N40/3 Left/right audio power amplifier

P82-7030-57